

American National Standard Z535.2 states "A visual alerting device in the form of a sign, label, decal, placard or other marking which advised the observer of the nature and degree of the potential hazard(s) which can cause an accident. It may also provide other directions to eliminate the hazards and may advise of the probable consequences of not avoiding the hazard"

Materials



Visually Intensive; Meets Latest ANSI Z535.2

Safety alert symbol →

International pictogram →

Lettering is left justified to enhance legibility →

Select your size and material for part number-example AN-1723 (7"x10" PL-plastic sign) →

7x10 AL AN-1721 FG AN-1722 PL AN-1723 VPO AN-1724	7x10 AL AN-3121 FG AN-3122 PL AN-3123 VPO AN-3124	7x10 AL AN-1821 FG AN-1822 PL AN-1823 VPO AN-1824	7x10 AL AN-3221 FG AN-3222 PL AN-3223 VPO AN-3224	7x10 AL AN-1921 FG AN-1922 PL AN-1923 VPO AN-1924	7x10 AL AN-2021 FG AN-2022 PL AN-2023 VPO AN-2024
10x14 AL AN-1731 FG AN-1732 PL AN-1733 VPO AN-1734	10x14 AL AN-3131 FG AN-3132 PL AN-3133 VPO AN-3134	10x14 AL AN-1831 FG AN-1832 PL AN-1833 VPO AN-1834	10x14 AL AN-3231 FG AN-3232 PL AN-3233 VPO AN-3234	10x14 AL AN-1931 FG AN-1932 PL AN-1933 VPO AN-1934	10x14 AL AN-2031 FG AN-2032 PL AN-2033 VPO AN-2034

7x10 AL AN-3321 FG AN-3322 PL AN-3323 VPO AN-3324	7x10 AL AN-2121 FG AN-2122 PL AN-2123 VPO AN-2124	7x10 AL AN-2221 FG AN-2222 PL AN-2223 VPO AN-2224	7x10 AL AN-2321 FG AN-2322 PL AN-2323 VPO AN-2324	7x10 AL AN-2421 FG AN-2422 PL AN-2423 VPO AN-2424	7x10 AL AN-3421 FG AN-3422 PL AN-3423 VPO AN-3424	7x10 AL AN-0121 FG AN-0122 PL AN-0123 VPO AN-0124	7x10 AL AN-4521 FG AN-4522 PL AN-4523 VPO AN-4524
10x14 AL AN-3331 FG AN-3332 PL AN-3333 VPO AN-3334	10x14 AL AN-2131 FG AN-2132 PL AN-2133 VPO AN-2134	10x14 AL AN-2231 FG AN-2232 PL AN-2233 VPO AN-2234	10x14 AL AN-2331 FG AN-2332 PL AN-2333 VPO AN-2334	10x14 AL AN-2431 FG AN-2432 PL AN-2433 VPO AN-2434	10x14 AL AN-3431 FG AN-3432 PL AN-3433 VPO AN-3434	10x14 AL AN-0131 FG AN-0132 PL AN-0133 VPO AN-0134	10x14 AL AN-4531 FG AN-4532 PL AN-4533 VPO AN-4534

7x10 AL AN-0221 FG AN-0222 PL AN-0223 VPO AN-0224	7x10 AL AN-0321 FG AN-0322 PL AN-0323 VPO AN-0324	7x10 AL AN-0421 FG AN-0422 PL AN-0423 VPO AN-0424	7x10 AL AN-0521 FG AN-0522 PL AN-0523 VPO AN-0524	7x10 AL AN-3521 FG AN-3522 PL AN-3523 VPO AN-3524	7x10 AL AN-3621 FG AN-3622 PL AN-3623 VPO AN-3624	7x10 AL AN-0621 FG AN-0622 PL AN-0623 VPO AN-0624	7x10 AL AN-0721 FG AN-0722 PL AN-0723 VPO AN-0724
10x14 AL AN-0231 FG AN-0232 PL AN-0233 VPO AN-0234	10x14 AL AN-0331 FG AN-0332 PL AN-0333 VPO AN-0334	10x14 AL AN-0431 FG AN-0432 PL AN-0433 VPO AN-0434	10x14 AL AN-0531 FG AN-0532 PL AN-0533 VPO AN-0534	10x14 AL AN-3531 FG AN-3532 PL AN-3533 VPO AN-3534	10x14 AL AN-3631 FG AN-3632 PL AN-3633 VPO AN-3634	10x14 AL AN-0631 FG AN-0632 PL AN-0633 VPO AN-0634	10x14 AL AN-0731 FG AN-0732 PL AN-0733 VPO AN-0734

7x10 AL AN-0821 FG AN-0822 PL AN-0823 VPO AN-0824	7x10 AL AN-0921 FG AN-0922 PL AN-0923 VPO AN-0924	7x10 AL AN-1021 FG AN-1022 PL AN-1023 VPO AN-1024	7x10 AL AN-1121 FG AN-1122 PL AN-1123 VPO AN-1124	7x10 AL AN-3821 FG AN-3822 PL AN-3823 VPO AN-3824	7x10 AL AN-3921 FG AN-3922 PL AN-3923 VPO AN-3924	7x10 AL AN-4021 FG AN-4022 PL AN-4023 VPO AN-4024	7x10 AL AN-3721 FG AN-3722 PL AN-3723 VPO AN-3724
10x14 AL AN-0831 FG AN-0832 PL AN-0833 VPO AN-0834	10x14 AL AN-0931 FG AN-0932 PL AN-0933 VPO AN-0934	10x14 AL AN-1031 FG AN-1032 PL AN-1033 VPO AN-1034	10x14 AL AN-1131 FG AN-1132 PL AN-1133 VPO AN-1134	10x14 AL AN-3831 FG AN-3832 PL AN-3833 VPO AN-3834	10x14 AL AN-3931 FG AN-3932 PL AN-3933 VPO AN-3934	10x14 AL AN-4031 FG AN-4032 PL AN-4033 VPO AN-4034	10x14 AL AN-3731 FG AN-3732 PL AN-3733 VPO AN-3734

- If You Don't See It, We Can Make It!
- Custom Jobs Our Specialty...Please Call For A Quote!

American National Standards Institute ANSI Signs

THE SIGNS OF A SAFE INDUSTRY

Visually Intensive; Meets Latest American National Standard Z535.2-1998

Materials



7x10 AL AN-2521
FG AN-2522
PL AN-2523
VPO AN-2524
10x14 AL AN-2531
FG AN-2532
PL AN-2533
VPO AN-2534



7x10 AL AN-2621
FG AN-2622
PL AN-2623
VPO AN-2624
10x14 AL AN-2631
FG AN-2632
PL AN-2633
VPO AN-2634



7x10 AL AN-2721
FG AN-2722
PL AN-2723
VPO AN-2724
10x14 AL AN-2731
FG AN-2732
PL AN-2733
VPO AN-2734



7x10 AL AN-2921
FG AN-2922
PL AN-2923
VPO AN-2924
10x14 AL AN-2931
FG AN-2932
PL AN-2933
VPO AN-2934



7x10 AL AN-4121
FG AN-4122
PL AN-4123
VPO AN-4124
10x14 AL AN-4131
FG AN-4132
PL AN-4133
VPO AN-4134



7x10 AL AN-4221
FG AN-4222
PL AN-4223
VPO AN-4224
10x14 AL AN-4231
FG AN-4232
PL AN-4233
VPO AN-4234




7x10 AL AN-2821
FG AN-2822
PL AN-2823
VPO AN-2824
10x14 AL AN-2831
FG AN-2832
PL AN-2833
VPO AN-2834



7x10 AL AN-4321
FG AN-4322
PL AN-4323
VPO AN-4324
10x14 AL AN-4331
FG AN-4332
PL AN-4333
VPO AN-4334



7x10 AL AN-4421
FG AN-4422
PL AN-4423
VPO AN-4424
10x14 AL AN-4431
FG AN-4432
PL AN-4433
VPO AN-4434



7x10 AL AN-3021
FG AN-3022
PL AN-3023
VPO AN-3024
10x14 AL AN-3031
FG AN-3032
PL AN-3033
VPO AN-3034




7x10 AL AN-1321
FG AN-1322
PL AN-1323
VPO AN-1324
10x14 AL AN-1331
FG AN-1332
PL AN-1333
VPO AN-1334



7x10 AL AN-1421
FG AN-1422
PL AN-1423
VPO AN-1424
10x14 AL AN-1431
FG AN-1432
PL AN-1433
VPO AN-1434



7x10 AL AN-4621
FG AN-4622
PL AN-4623
VPO AN-4624
10x14 AL AN-4631
FG AN-4632
PL AN-4633
VPO AN-4634



7x10 AL AN-4721
FG AN-4722
PL AN-4723
VPO AN-4724
10x14 AL AN-4731
FG AN-4732
PL AN-4733
VPO AN-4734



7x10 AL AN-1521
FG AN-1522
PL AN-1523
VPO AN-1524
10x14 AL AN-1531
FG AN-1532
PL AN-1533
VPO AN-1534



7x10 AL AN-1621
FG AN-1622
PL AN-1623
VPO AN-1624
10x14 AL AN-1631
FG AN-1632
PL AN-1633
VPO AN-1634

ANSI Graphic Machine Labels

International machine safety labels are available in three sizes:

1.75" x 2.5" - 2" x 3" - 3" x 5"




1.7x2.5 VPO ML-011
2x3 VPO ML-012
3x5 VPO ML-013




1.7x2.5 VPO ML-021
2x3 VPO ML-022
3x5 VPO ML-023



1.7x2.5 VPO ML-031
2x3 VPO ML-032
3x5 VPO ML-033



1.7x2.5 VPO ML-041
2x3 VPO ML-042
3x5 VPO ML-043



1.7x2.5 VPO ML-051
2x3 VPO ML-052
3x5 VPO ML-053



1.7x2.5 VPO ML-061
2x3 VPO ML-062
3x5 VPO ML-063



1.7x2.5 VPO ML-071
2x3 VPO ML-072
3x5 VPO ML-073



1.7x2.5 VPO ML-081
2x3 VPO ML-082
3x5 VPO ML-083




1.7x2.5 VPO ML-091
2x3 VPO ML-092
3x5 VPO ML-093



1.7x2.5 VPO ML-101
2x3 VPO ML-102
3x5 VPO ML-103




1.7x2.5 VPO ML-111
2x3 VPO ML-112
3x5 VPO ML-113




1.7x2.5 VPO ML-121
2x3 VPO ML-122
3x5 VPO ML-123



1.7x2.5 VPO ML-141
2x3 VPO ML-142
3x5 VPO ML-143



1.7x2.5 VPO ML-151
2x3 VPO ML-152
3x5 VPO ML-153



1.7x2.5 VPO ML-161
2x3 VPO ML-162
3x5 VPO ML-163



1.7x2.5 VPO ML-171
2x3 VPO ML-172
3x5 VPO ML-173



1.7x2.5 VPO ML-181
2x3 VPO ML-182
3x5 VPO ML-183



1.7x2.5 VPO ML-191
2x3 VPO ML-192
3x5 VPO ML-193

ANSI Graphic Machine Labels
All Sizes

ALL SIZES
5 PACK

American National Standard ANSI Z535.4 2002 provides a uniform layout for safety labels and signs that is applicable to all products in all industries that may pose a safety question except safety labeling of chemicals and the transportation of dangerous goods."

THE SIGNS OF A SAFE INDUSTRY

Electrical shock, arc flash, and arc blast are hazards associated with working on or in close proximity to energized equipment. All three types can and do occur in industrial facilities.

The three applicable regulatory standards are OSHA 29 CFR 1910 subpart S-Electrical, NFPA 70E-2000 edition, and NEC 2002.


Arc Flash Protection Labels




3x5 VPO AF-651114
7x10 AL AF-651121
FG AF-651122
PL AF-651123
VPO AF-651124
10x14 AL AF-651131
FG AF-651132
PL AF-651133
VPO AF-651134



3x5 VPO AF-651214
7x10 AL AF-651221
FG AF-651222
PL AF-651223
VPO AF-651224
10x14 AL AF-651231
FG AF-651232
PL AF-651233
VPO AF-651234




3x5 VPO AF-651314
7x10 AL AF-651321
FG AF-651322
PL AF-651323
VPO AF-651324
10x14 AL AF-651331
FG AF-651332
PL AF-651333
VPO AF-651334




3x5 VPO AF-651414
7x10 AL AF-651421
FG AF-651422
PL AF-651423
VPO AF-651424
10x14 AL AF-651431
FG AF-651432
PL AF-651433
VPO AF-651434




Arc flash accidents and explosions cause more than 2,000 injuries per year according to the NFPA.



3x5 VPO AF-651714
7x10 AL AF-651721
FG AF-651722
PL AF-651723
VPO AF-651724
10x14 AL AF-651731
FG AF-651732
PL AF-651733
VPO AF-651734



3x5 VPO AF-651814
7x10 AL AF-651821
FG AF-651822
PL AF-651823
VPO AF-651824
10x14 AL AF-651831
FG AF-651832
PL AF-651833
VPO AF-651834




3x5 VPO AF-651914
7x10 AL AF-651921
FG AF-651922
PL AF-651923
VPO AF-651924
10x14 AL AF-651931
FG AF-651932
PL AF-651933
VPO AF-651934



3x5 VPO AF-652014
7x10 AL AF-652021
FG AF-652022
PL AF-652023
VPO AF-652024
10x14 AL AF-652031
FG AF-652032
PL AF-652033
VPO AF-652034



3x5 VPO AF-652114
7x10 AL AF-652121
FG AF-652122
PL AF-652123
VPO AF-652124
10x14 AL AF-652131
FG AF-652132
PL AF-652133
VPO AF-652134



3x5 VPO AF-651514
7x10 AL AF-651521
FG AF-651522
PL AF-651523
VPO AF-651524
10x14 AL AF-651531
FG AF-651532
PL AF-651533
VPO AF-651534



3x5 VPO AF-651614
7x10 AL AF-651621
FG AF-651622
PL AF-651623
VPO AF-651624
10x14 AL AF-651631
FG AF-651632
PL AF-651633
VPO AF-651634



4x12 VPO AF-652214



4x12 VPO AF-652314

Authorized Personnel



3x5 VPO D-002114
7x10 AL D-002121
FG D-002122
PL D-002123
VPO D-002124
10x14 AL D-002131
FG D-002132
PL D-002133
VPO D-002134
14x20 AL D-002141
PL D-002143
VPO D-002144




3x5 VPO D-001014
7x10 AL D-001021
FG D-001022
PL D-001023
VPO D-001024
10x14 AL D-001031
FG D-001032
PL D-001033
VPO D-001034
14x20 AL D-001041
PL D-001043
VPO D-001044



3x5 VPO W-966014
7x10 AL W-966021
FG W-966022
PL W-966023
VPO W-966024
10x14 AL W-966031
FG W-966032
PL W-966033
VPO W-966034
14x20 AL W-966041
PL W-966043
VPO W-966044



3x5 VPO N-001314
7x10 AL N-001321
FG N-001322
PL N-001323
VPO N-001324
10x14 AL N-001331
FG N-001332
PL N-001333
VPO N-001334
14x20 AL N-001341
PL N-001343
VPO N-001344



3x5 VPO N-001514
7x10 AL N-001521
FG N-001522
PL N-001523
VPO N-001524
10x14 AL N-001531
FG N-001532
PL N-001533
VPO N-001534
14x20 AL N-001541
PL N-001543
VPO N-001544



3x5 VPO G-000314
7x10 AL G-000321
FG G-000322
PL G-000323
VPO G-000324
10x14 AL G-000331
FG G-000332
PL G-000333
VPO G-000334
14x20 AL G-000341
PL G-000343
VPO G-000344

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

Asbestos & Lead Abatement

THE SIGNS OF A SAFE INDUSTRY

OSHA §1926.1101(k)(7)(i) states "Warning signs that demarcate the regulated area shall be provided and displayed at each location where a regulated area is required to be established by paragraph (e) of this section. Signs shall be posted at such a distance from such a location that an employee may read the signs and take necessary protective steps before entering the area marked by the signs."


Asbestos Labels Self-adhesive paper labels 3" x 5" • 500 per roll




SAHL-12




SAHL-13



SL-9902



SL-9903



SL-37



SL-36



SL-9901



SL-9904



SL-9906



SL-9905

Asbestos and Lead Abatement Signs



Barricade Tape

3 mil thick • 3" x 1000' Rolls

SBT-46 - DANGER ASBESTOS (red/black copy)
 SBT-47 - DANGER ASBESTOS (as shown white w/cautionary information)

ASBESTOS
 CANCER AND LUNG DISEASE HAZARD
 AUTHORIZED PERSONNEL ONLY
 RESPIRATORS AND
 PROTECTIVE CLOTHING
 ARE REQUIRED IN THIS AREA

See page 120 for more barricade tapes

Material	Sign Type	Message	Size	Material	Sign Type	Message	Size	Material	Sign Type	Message	Size	Material	Sign Type	Message	Size
3x5 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450114	3x5 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450614	3x5 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000914	3x5 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001914
7x10 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450121	7x10 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450621	7x10 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000921	7x10 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001921
7x10 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450122	7x10 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450622	7x10 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000922	7x10 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001922
7x10 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450123	7x10 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450623	7x10 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000923	7x10 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001923
7x10 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450124	7x10 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450624	7x10 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000924	7x10 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001924
10x14 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450131	10x14 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450631	10x14 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000931	10x14 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001931
10x14 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450132	10x14 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450632	10x14 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000932	10x14 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001932
10x14 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450133	10x14 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450633	10x14 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000933	10x14 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001933
10x14 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450134	10x14 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450634	10x14 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000934	10x14 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001934
14x20 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450141	14x20 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450641	14x20 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000941	14x20 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001941
14x20 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450143	14x20 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450643	14x20 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000943	14x20 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001943
14x20 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450144	14x20 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450644	14x20 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000944	14x20 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001944
3x5 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450114	3x5 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450614	3x5 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000914	3x5 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001914
7x10 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450121	7x10 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450621	7x10 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000921	7x10 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001921
7x10 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450122	7x10 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450622	7x10 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000922	7x10 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001922
7x10 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450123	7x10 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450623	7x10 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000923	7x10 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001923
7x10 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450124	7x10 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450624	7x10 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000924	7x10 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001924
10x14 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450131	10x14 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450631	10x14 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000931	10x14 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001931
10x14 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450132	10x14 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450632	10x14 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000932	10x14 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001932
10x14 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450133	10x14 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450633	10x14 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000933	10x14 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001933
10x14 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450134	10x14 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450634	10x14 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000934	10x14 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001934
14x20 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450141	14x20 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450641	14x20 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000941	14x20 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001941
14x20 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450143	14x20 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450643	14x20 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000943	14x20 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001943
14x20 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450144	14x20 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450644	14x20 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000944	14x20 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001944

Paper Signs 100 PER PACK

PS-01 (11" x 17")
PS-04 (14" x 20")


PS-02 11" X 17"

SPANISH

PS-03 11" x 17"

Asbestos Floor Sign

These signs are printed on both sides for two-way traffic flow. Floor Stand Signs are weather resistant for indoor/outdoor usage. Each sign is printed with two messages. Reverse the sign to display the second message. Sturdy 12"x20" (30 x 51 cm) corrugated polyethylene. Weight 1 lb. (.45kg)



FFS-12

See page 50 for more floor stands

- If You Don't See It, We Can Make It!
- Custom Jobs Our Specialty...Please Call For A Quote!

CAUTION

OSHA§1910.145(c)(2)(i) states "Caution signs shall be used only to warn against potential hazards or to Caution against unsafe practices." (ii) states "All employees shall be instructed that Caution signs indicate a possible hazard against which proper precaution should be taken."
This heading should not be used when there is a possibility of death or serious injury.

THE SIGNS OF A SAFE INDUSTRY

MATERIALS



CAUTION
ACID

3x5 VPO C-000114
7x10 AL C-000121
FG C-000122
PL C-000123
VPO C-000124
10x14 AL C-000131
FG C-000132
PL C-000133
VPO C-000134
14x20 AL C-000141
PL C-000143
VPO C-000144

CAUTION
**ACID
BE CAREFUL**

3x5 VPO C-000214
7x10 AL C-000221
FG C-000222
PL C-000223
VPO C-000224
10x14 AL C-000231
FG C-000232
PL C-000233
VPO C-000234
14x20 AL C-000241
PL C-000243
VPO C-000244

CAUTION
**AREA IN FRONT OF
ELECTRICAL PANEL
MUST BE KEPT CLEAR
FOR 36 INCHES
OSHA REGULATIONS**

3x5 VPO C-000614
7x10 AL C-000621
FG C-000622
PL C-000623
VPO C-000624
10x14 AL C-000631
FG C-000632
PL C-000633
VPO C-000634
14x20 AL C-000641
PL C-000643
VPO C-000644

CAUTION
**ASBESTOS HAZARD DO
NOT DISTURB WITHOUT
PROPER TRAINING AND
EQUIPMENT**

3x5 VPO C-000914
7x10 AL C-000921
FG C-000922
PL C-000923
VPO C-000924
10x14 AL C-000931
FG C-000932
PL C-000933
VPO C-000934
14x20 AL C-000941
PL C-000943
VPO C-000944

CAUTION
**ATTACH
GROUNDING
WIRE CLIPS**

3x5 VPO C-001114
7x10 AL C-001121
FG C-001122
PL C-001123
VPO C-001124
10x14 AL C-001131
FG C-001132
PL C-001133
VPO C-001134
14x20 AL C-001141
PL C-001143
VPO C-001144

CAUTION
**AUTOMATIC
EQUIPMENT
WILL START AT
ANY TIME**

3x5 VPO C-001214
7x10 AL C-001221
FG C-001222
PL C-001223
VPO C-001224
10x14 AL C-001231
FG C-001232
PL C-001233
VPO C-001234
14x20 AL C-001241
PL C-001243
VPO C-001244

CAUTION
**BATTERY CHARGING
STATION NO SMOKING
OR OPEN FLAMES**

3x5 VPO C-050114
7x10 AL C-050121
FG C-050122
PL C-050123
VPO C-050124
10x14 AL C-050131
FG C-050132
PL C-050133
VPO C-050134
14x20 AL C-050141
PL C-050143
VPO C-050144

CAUTION
**BEFORE ENTERING TEST FOR
EXPLOSIVE ATMOSPHERE
TEST FOR OXYGEN
DEFICIENCY SUPPLY FRESH
AIR TO WORK AREA**

3x5 VPO C-050314
7x10 AL C-050321
FG C-050322
PL C-050323
VPO C-050324
10x14 AL C-050331
FG C-050332
PL C-050333
VPO C-050334
14x20 AL C-050341
PL C-050343
VPO C-050344

CAUTION
**BEFORE PROCEEDING WITH
REPAIR WORK ALL SOURCES OF
POWER TO THE MACHINE MUST
BE TAGGED OUT AND/OR SECURED
WITH A LOCKING DEVICE**

3x5 VPO C-050414
7x10 AL C-050421
FG C-050422
PL C-050423
VPO C-050424
10x14 AL C-050431
FG C-050432
PL C-050433
VPO C-050434
14x20 AL C-050441
PL C-050443
VPO C-050444

CAUTION
**BEFORE YOU
START
LOCKOUT FOR
SAFETY**

3x5 VPO C-050514
7x10 AL C-050521
FG C-050522
PL C-050523
VPO C-050524
10x14 AL C-050531
FG C-050532
PL C-050533
VPO C-050534
14x20 AL C-050541
PL C-050543
VPO C-050544

CAUTION
**BEND KNEES
WHEN LIFTING**

3x5 VPO C-050614
7x10 AL C-050621
FG C-050622
PL C-050623
VPO C-050624
10x14 AL C-050631
FG C-050632
PL C-050633
VPO C-050634
14x20 AL C-050641
PL C-050643
VPO C-050644

CAUTION
**BEWARE OF
FALLING
OBJECTS**

3x5 VPO C-050714
7x10 AL C-050721
FG C-050722
PL C-050723
VPO C-050724
10x14 AL C-050731
FG C-050732
PL C-050733
VPO C-050734
14x20 AL C-050741
PL C-050743
VPO C-050744

CAUTION
**BUMP HAT
REQUIRED**

3x5 VPO C-050814
7x10 AL C-050821
FG C-050822
PL C-050823
VPO C-050824
10x14 AL C-050831
FG C-050832
PL C-050833
VPO C-050834
14x20 AL C-050841
PL C-050843
VPO C-050844

CAUTION
**BURIED GAS
LINE**

3x5 VPO C-050914
7x10 AL C-050921
FG C-050922
PL C-050923
VPO C-050924
10x14 AL C-050931
FG C-050932
PL C-050933
VPO C-050934
14x20 AL C-050941
PL C-050943
VPO C-050944

CAUTION
**BURIED
WATER LINE**

3x5 VPO C-051114
7x10 AL C-051121
FG C-051122
PL C-051123
VPO C-051124
10x14 AL C-051131
FG C-051132
PL C-051133
VPO C-051134
14x20 AL C-051141
PL C-051143
VPO C-051144

CAUTION

3x5 VPO C-080614
7x10 AL C-080621
FG C-080622
PL C-080623
VPO C-080624
10x14 AL C-080631
FG C-080632
PL C-080633
VPO C-080634
14x20 AL C-080641
PL C-080643
VPO C-080644

CAUTION
**CARBON
MONOXIDE
MAY BE PRESENT**

3x5 VPO C-080214
7x10 AL C-080221
FG C-080222
PL C-080223
VPO C-080224
10x14 AL C-080231
FG C-080232
PL C-080233
VPO C-080234
14x20 AL C-080241
PL C-080243
VPO C-080244

CAUTION
CAUSTIC

3x5 VPO C-080314
7x10 AL C-080321
FG C-080322
PL C-080323
VPO C-080324
10x14 AL C-080331
FG C-080332
PL C-080333
VPO C-080334
14x20 AL C-080341
PL C-080343
VPO C-080344

CAUTION
**CAUSTIC SODA
AVOID SKIN OR EYE CONTACT
AVOID INHALATION OR INGESTION
CAN CAUSE SEVERE BURNS WEAR
PROTECTIVE CLOTHING WHEN WORKING
WITH CAUSTIC SODA IF SKIN OR EYES
ARE CONTACTED FLUSH WITH
WATER FOR 15 MIN.**

3x5 VPO C-080414
7x10 AL C-080421
FG C-080422
PL C-080423
VPO C-080424
10x14 AL C-080431
FG C-080432
PL C-080433
VPO C-080434
14x20 AL C-080441
PL C-080443
VPO C-080444

CAUTION
**CHAIN GAS
CYLINDERS**

3x5 VPO C-080814
7x10 AL C-080821
FG C-080822
PL C-080823
VPO C-080824
10x14 AL C-080831
FG C-080832
PL C-080833
VPO C-080834
14x20 AL C-080841
PL C-080843
VPO C-080844

CAUTION
**CHEMICAL
GOGGLE AREA**

3x5 VPO C-080914
7x10 AL C-080921
FG C-080922
PL C-080923
VPO C-080924
10x14 AL C-080931
FG C-080932
PL C-080933
VPO C-080934
14x20 AL C-080941
PL C-080943
VPO C-080944

CAUTION
CHEMICALS

3x5 VPO C-081114
7x10 AL C-081121
FG C-081122
PL C-081123
VPO C-081124
10x14 AL C-081131
FG C-081132
PL C-081133
VPO C-081134
14x20 AL C-081141
PL C-081143
VPO C-081144

CAUTION
**CHLORINE
AREA**

3x5 VPO C-081214
7x10 AL C-081221
FG C-081222
PL C-081223
VPO C-081224
10x14 AL C-081231
FG C-081232
PL C-081233
VPO C-081234
14x20 AL C-081241
PL C-081243
VPO C-081244

CAUTION
**CHLORINE
AVOID INHALATION AND SKIN OR
EYE CONTACT INHALATION WILL CAUSE
SHORTNESS OF BREATH AND NAUSEA
A NIOSH/MSHA APPROVED CHEMICAL
CARTRIDGE TYPE ESCAPE RESPIRATOR
SHOULD BE CARRIED AT ALL TIMES
WHEN HANDLING CHLORINE**

3x5 VPO C-081314
7x10 AL C-081321
FG C-081322
PL C-081323
VPO C-081324
10x14 AL C-081331
FG C-081332
PL C-081333
VPO C-081334
14x20 AL C-081341
PL C-081343
VPO C-081344

CAUTION
**CLASS II HELIUM
NEON LASER
DO NOT STARE
INTO BEAM**

3x5 VPO C-081414
7x10 AL C-081421
FG C-081422
PL C-081423
VPO C-081424
10x14 AL C-081431
FG C-081432
PL C-081433
VPO C-081434
14x20 AL C-081441
PL C-081443
VPO C-081444

CAUTION
**CLEARANCE
___FT. ___IN.**

3x5 VPO C-081514
7x10 AL C-081521
FG C-081522
PL C-081523
VPO C-081524
10x14 AL C-081531
FG C-081532
PL C-081533
VPO C-081534
14x20 AL C-081541
PL C-081543
VPO C-081544

CAUTION
**CLOSE
CLEARANCE**

3x5 VPO C-081614
7x10 AL C-081621
FG C-081622
PL C-081623
VPO C-081624
10x14 AL C-081631
FG C-081632
PL C-081633
VPO C-081634
14x20 AL C-081641
PL C-081643
VPO C-081644

CAUTION
**CLOTHING CONTAMINATED
WITH LEAD DO NOT
REMOVE DUST BY
BLOWING**

3x5 VPO C-081714
7x10 AL C-081721
FG C-081722
PL C-081723
VPO C-081724
10x14 AL C-081731
FG C-081732
PL C-081733
VPO C-081734
14x20 AL C-081741
PL C-081743
VPO C-081744

THE SIGNS OF A SAFE INDUSTRY



CAUTION

<p>CAUTION</p> <p>CLOTHING CONTAMINATED WITH LEAD DO NOT REMOVE DUST BY BLOWING OR SHAKING DISPOSE OF LEAD CONTAMINATED WASH WATER IN ACCORDANCE WITH APPLICABLE LOCAL STATE OR FEDERAL REGULATIONS</p>	<p>CAUTION</p> <p>COMPRESSED AIR</p>	<p>CAUTION</p> <p>CONFINED SPACE</p>	<p>CAUTION</p> <p>CONFINED SPACE DO NOT ENTER WITHOUT OBTAINING PERMIT NO. _____</p>	<p>CAUTION</p> <p>CONFINED SPACE ENTER BY PERMIT ONLY</p>	<p>CAUTION</p> <p>CONFINED SPACE ENTRY PERMIT REQUIRED CALL SECURITY</p>	<p>CAUTION</p> <p>CONFINED SPACE ENTRY PERMIT REQUIRED CONTACT YOUR SUPERVISOR</p>
<p>3x5 VPO C-081814 7x10 AL C-081821 FG C-081822 PL C-081823 VPO C-081824 10x14 AL C-081831 FG C-081832 PL C-081833 VPO C-081834 14x20 AL C-081841 PL C-081843 VPO C-081844</p>	<p>3x5 VPO C-081914 7x10 AL C-081921 FG C-081922 PL C-081923 VPO C-081924 10x14 AL C-081931 FG C-081932 PL C-081933 VPO C-081934 14x20 AL C-081941 PL C-081943 VPO C-081944</p>	<p>3x5 VPO C-082014 7x10 AL C-082021 FG C-082022 PL C-082023 VPO C-082024 10x14 AL C-082031 FG C-082032 PL C-082033 VPO C-082034 14x20 AL C-082041 PL C-082043 VPO C-082044</p>	<p>3x5 VPO C-082214 7x10 AL C-082221 FG C-082222 PL C-082223 VPO C-082224 10x14 AL C-082231 FG C-082232 PL C-082233 VPO C-082234 14x20 AL C-082241 PL C-082243 VPO C-082244</p>	<p>3x5 VPO C-082314 7x10 AL C-082321 FG C-082322 PL C-082323 VPO C-082324 10x14 AL C-082331 FG C-082332 PL C-082333 VPO C-082334 14x20 AL C-082341 PL C-082343 VPO C-082344</p>	<p>3x5 VPO C-082414 7x10 AL C-082421 FG C-082422 PL C-082423 VPO C-082424 10x14 AL C-082431 FG C-082432 PL C-082433 VPO C-082434 14x20 AL C-082441 PL C-082443 VPO C-082444</p>	<p>3x5 VPO C-082514 7x10 AL C-082521 FG C-082522 PL C-082523 VPO C-082524 10x14 AL C-082531 FG C-082532 PL C-082533 VPO C-082534 14x20 AL C-082541 PL C-082543 VPO C-082544</p>

<p>CAUTION</p> <p>CONFINED SPACE NO. _____ ENTRY PERMIT REQUIRED CALL _____</p>	<p>CAUTION</p> <p>CONGESTED AISLE</p>	<p>CAUTION</p> <p>CONGESTED AREA</p>	<p>CAUTION</p> <p>CONNECT GROUND WIRE BEFORE USING</p>	<p>CAUTION</p> <p>CONSTRUCTION AREA</p>	<p>CAUTION</p> <p>CONTAINS ASBESTOS FIBERS AVOID CREATING DUST BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM</p>	<p>CAUTION</p> <p>CONTAINS CORROSIVE LIQUID</p>
<p>3x5 VPO C-082614 7x10 AL C-082621 FG C-082622 PL C-082623 VPO C-082624 10x14 AL C-082631 FG C-082632 PL C-082633 VPO C-082634 14x20 AL C-082641 PL C-082643 VPO C-082644</p>	<p>3x5 VPO C-082714 7x10 AL C-082721 FG C-082722 PL C-082723 VPO C-082724 10x14 AL C-082731 FG C-082732 PL C-082733 VPO C-082734 14x20 AL C-082741 PL C-082743 VPO C-082744</p>	<p>3x5 VPO C-082814 7x10 AL C-082821 FG C-082822 PL C-082823 VPO C-082824 10x14 AL C-082831 FG C-082832 PL C-082833 VPO C-082834 14x20 AL C-082841 PL C-082843 VPO C-082844</p>	<p>3x5 VPO C-082914 7x10 AL C-082921 FG C-082922 PL C-082923 VPO C-082924 10x14 AL C-082931 FG C-082932 PL C-082933 VPO C-082934 14x20 AL C-082941 PL C-082943 VPO C-082944</p>	<p>3x5 VPO C-083014 7x10 AL C-083021 FG C-083022 PL C-083023 VPO C-083024 10x14 AL C-083031 FG C-083032 PL C-083033 VPO C-083034 14x20 AL C-083041 PL C-083043 VPO C-083044</p>	<p>3x5 VPO C-083114 7x10 AL C-083121 FG C-083122 PL C-083123 VPO C-083124 10x14 AL C-083131 FG C-083132 PL C-083133 VPO C-083134 14x20 AL C-083141 PL C-083143 VPO C-083144</p>	<p>3x5 VPO C-083214 7x10 AL C-083221 FG C-083222 PL C-083223 VPO C-083224 10x14 AL C-083231 FG C-083232 PL C-083233 VPO C-083234 14x20 AL C-083241 PL C-083243 VPO C-083244</p>

<p>CAUTION</p> <p>CONTAINS ETHYLENE OXIDE CANCER AND REPRODUCTIVE HAZARD AVOID BREATHING VAPORS</p>	<p>CAUTION</p> <p>CONTAINS HAZARDOUS MATERIAL SEE MSDS FILE</p>	<p>CAUTION</p> <p>CONTAINS PCB CANCER HAZARD</p>	<p>CAUTION</p> <p>CONVEYOR MAY START WITHOUT WARNING</p>	<p>CAUTION</p> <p>CORROSIVE MATERIAL IN USE</p>	<p>CAUTION</p> <p>CUTTING AND WELDING PERMIT REQUIRED IN THIS AREA</p>	<p>CAUTION</p> <p>DEPOSIT MATCHES AND ALL SMOKING MATERIAL IN THIS RECEPTACLE</p>
<p>3x5 VPO C-083314 7x10 AL C-083321 FG C-083322 PL C-083323 VPO C-083324 10x14 AL C-083331 FG C-083332 PL C-083333 VPO C-083334 14x20 AL C-083341 PL C-083343 VPO C-083344</p>	<p>3x5 VPO C-083414 7x10 AL C-083421 FG C-083422 PL C-083423 VPO C-083424 10x14 AL C-083431 FG C-083432 PL C-083433 VPO C-083434 14x20 AL C-083441 PL C-083443 VPO C-083444</p>	<p>3x5 VPO C-083514 7x10 AL C-083521 FG C-083522 PL C-083523 VPO C-083524 10x14 AL C-083531 FG C-083532 PL C-083533 VPO C-083534 14x20 AL C-083541 PL C-083543 VPO C-083544</p>	<p>3x5 VPO C-083614 7x10 AL C-083621 FG C-083622 PL C-083623 VPO C-083624 10x14 AL C-083631 FG C-083632 PL C-083633 VPO C-083634 14x20 AL C-083641 PL C-083643 VPO C-083644</p>	<p>3x5 VPO C-083714 7x10 AL C-083721 FG C-083722 PL C-083723 VPO C-083724 10x14 AL C-083731 FG C-083732 PL C-083733 VPO C-083734 14x20 AL C-083741 PL C-083743 VPO C-083744</p>	<p>3x5 VPO C-083914 7x10 AL C-083921 FG C-083922 PL C-083923 VPO C-083924 10x14 AL C-083931 FG C-083932 PL C-083933 VPO C-083934 14x20 AL C-083941 PL C-083943 VPO C-083944</p>	<p>3x5 VPO C-110114 7x10 AL C-110121 FG C-110122 PL C-110123 VPO C-110124 10x14 AL C-110131 FG C-110132 PL C-110133 VPO C-110134 14x20 AL C-110141 PL C-110143 VPO C-110144</p>

<p>CAUTION</p> <p>DISCONNECT POWER BEFORE SERVICING</p>	<p>CAUTION</p> <p>DO NOT ENTER</p>	<p>CAUTION</p> <p>DO NOT BACK THIS VEHICLE UNLESS YOU ARE SURE IT IS SAFE AND CLEAR</p>	<p>CAUTION</p> <p>DO NOT ENTER THIS SHOP WITHOUT EYE PROTECTION</p>	<p>CAUTION</p> <p>DO NOT ENTER WITHOUT AIR PAC WHEN CHLORINE ALARM IS ON</p>	<p>CAUTION</p> <p>DO NOT ENTER WHEN RED LIGHT IS FLASHING</p>	<p>CAUTION</p> <p>DO NOT ENTER WHILE MACHINERY IN MOTION</p>
<p>3x5 VPO C-110314 7x10 AL C-110321 FG C-110322 PL C-110323 VPO C-110324 10x14 AL C-110331 FG C-110332 PL C-110333 VPO C-110334 14x20 AL C-110341 PL C-110343 VPO C-110344</p>	<p>3x5 VPO C-110414 7x10 AL C-110421 FG C-110422 PL C-110423 VPO C-110424 10x14 AL C-110431 FG C-110432 PL C-110433 VPO C-110434 14x20 AL C-110441 PL C-110443 VPO C-110444</p>	<p>3x5 VPO C-110514 7x10 AL C-110521 FG C-110522 PL C-110523 VPO C-110524 10x14 AL C-110531 FG C-110532 PL C-110533 VPO C-110534 14x20 AL C-110541 PL C-110543 VPO C-110544</p>	<p>3x5 VPO C-110914 7x10 AL C-110921 FG C-110922 PL C-110923 VPO C-110924 10x14 AL C-110931 FG C-110932 PL C-110933 VPO C-110934 14x20 AL C-110941 PL C-110943 VPO C-110944</p>	<p>3x5 VPO C-111014 7x10 AL C-111021 FG C-111022 PL C-111023 VPO C-111024 10x14 AL C-111031 FG C-111032 PL C-111033 VPO C-111034 14x20 AL C-111041 PL C-111043 VPO C-111044</p>	<p>3x5 VPO C-111114 7x10 AL C-111121 FG C-111122 PL C-111123 VPO C-111124 10x14 AL C-111131 FG C-111132 PL C-111133 VPO C-111134 14x20 AL C-111141 PL C-111143 VPO C-111144</p>	<p>3x5 VPO C-111214 7x10 AL C-111221 FG C-111222 PL C-111223 VPO C-111224 10x14 AL C-111231 FG C-111232 PL C-111233 VPO C-111234 14x20 AL C-111241 PL C-111243 VPO C-111244</p>

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

CAUTION

THE SIGNS OF A SAFE INDUSTRY



<p>CAUTION</p> <p>DO NOT ENTER WITHOUT A CONFINED SPACE PERMIT</p> <p>3x5 VPO C-111514 7x10 AL C-111521 FG C-111522 PL C-111523 VPO C-111524 10x14 AL C-111531 FG C-111532 PL C-111533 VPO C-111534 14x20 AL C-111541 PL C-111543 VPO C-111544</p>	<p>CAUTION</p> <p>DO NOT ENTER WITHOUT EYE PROTECTION</p> <p>3x5 VPO C-111614 7x10 AL C-111621 FG C-111622 PL C-111623 VPO C-111624 10x14 AL C-111631 FG C-111632 PL C-111633 VPO C-111634 14x20 AL C-111641 PL C-111643 VPO C-111644</p>	<p>CAUTION</p> <p>DO NOT GRIND IF CLEARANCE BETWEEN WHEEL AND TOOL REST IS MORE THAN 1/16 INCH</p> <p>3x5 VPO C-111814 7x10 AL C-111821 FG C-111822 PL C-111823 VPO C-111824 10x14 AL C-111831 FG C-111832 PL C-111833 VPO C-111834 14x20 AL C-111841 PL C-111843 VPO C-111844</p>	<p>CAUTION</p> <p>DO NOT GRIND IF CLEARANCE BETWEEN WHEEL AND TOOL REST IS MORE THAN 1/8 INCH</p> <p>3x5 VPO C-111914 7x10 AL C-111921 FG C-111922 PL C-111923 VPO C-111924 10x14 AL C-111931 FG C-111932 PL C-111933 VPO C-111934 14x20 AL C-111941 PL C-111943 VPO C-111944</p>	<p>CAUTION</p> <p>DO NOT OPERATE MACHINERY WITHOUT GUARDS. DO NOT REMOVE GUARDS, CLEAN, OIL OR REPAIR MACHINERY WHILE IN MOTION</p> <p>3x5 VPO C-112114 7x10 AL C-112121 FG C-112122 PL C-112123 VPO C-112124 10x14 AL C-112131 FG C-112132 PL C-112133 VPO C-112134 14x20 AL C-112141 PL C-112143 VPO C-112144</p>	<p>CAUTION</p> <p>DO NOT OPERATE THIS EQUIPMENT WITHOUT EAR PROTECTION</p> <p>3x5 VPO C-112214 7x10 AL C-112221 FG C-112222 PL C-112223 VPO C-112224 10x14 AL C-112231 FG C-112232 PL C-112233 VPO C-112234 14x20 AL C-112241 PL C-112243 VPO C-112244</p>	<p>CAUTION</p> <p>DO NOT OPERATE THIS MACHINE WITHOUT EYE PROTECTION</p> <p>3x5 VPO C-112414 7x10 AL C-112421 FG C-112422 PL C-112423 VPO C-112424 10x14 AL C-112431 FG C-112432 PL C-112433 VPO C-112434 14x20 AL C-112441 PL C-112443 VPO C-112444</p>
<p>CAUTION</p> <p>DO NOT OPERATE THIS MACHINE WITHOUT GUARDS IN PLACE</p> <p>3x5 VPO C-112614 7x10 AL C-112621 FG C-112622 PL C-112623 VPO C-112624 10x14 AL C-112631 FG C-112632 PL C-112633 VPO C-112634 14x20 AL C-112641 PL C-112643 VPO C-112644</p>	<p>CAUTION</p> <p>DO NOT OPERATE WITHOUT GUARD</p> <p>3x5 VPO C-112714 7x10 AL C-112721 FG C-112722 PL C-112723 VPO C-112724 10x14 AL C-112731 FG C-112732 PL C-112733 VPO C-112734 14x20 AL C-112741 PL C-112743 VPO C-112744</p>	<p>CAUTION</p> <p>DO NOT STARE INTO BEAM HELIUM NEON LASER</p> <p>3x5 VPO C-113014 7x10 AL C-113021 FG C-113022 PL C-113023 VPO C-113024 10x14 AL C-113031 FG C-113032 PL C-113033 VPO C-113034 14x20 AL C-113041 PL C-113043 VPO C-113044</p>	<p>CAUTION</p> <p>DO NOT STARE INTO BEAM LASER IN USE</p> <p>3x5 VPO C-113114 7x10 AL C-113121 FG C-113122 PL C-113123 VPO C-113124 10x14 AL C-113131 FG C-113132 PL C-113133 VPO C-113134 14x20 AL C-113141 PL C-113143 VPO C-113144</p>	<p>CAUTION</p> <p>DO NOT TALK TO OPERATOR WHILE MACHINE IS IN MOTION</p> <p>3x5 VPO C-113214 7x10 AL C-113221 FG C-113222 PL C-113223 VPO C-113224 10x14 AL C-113231 FG C-113232 PL C-113233 VPO C-113234 14x20 AL C-113241 PL C-113243 VPO C-113244</p>	<p>CAUTION</p> <p>DO NOT THROW MATCHES, RUBBISH, CIGARETTE OR CIGAR STUBS IN URINALS</p> <p>3x5 VPO C-113314 7x10 AL C-113321 FG C-113322 PL C-113323 VPO C-113324 10x14 AL C-113331 FG C-113332 PL C-113333 VPO C-113334 14x20 AL C-113341 PL C-113343 VPO C-113344</p>	<p>CAUTION</p> <p>DO NOT USE COMPRESSED AIR TO BLOW OFF CLOTHING</p> <p>3x5 VPO C-113414 7x10 AL C-113421 FG C-113422 PL C-113423 VPO C-113424 10x14 AL C-113431 FG C-113432 PL C-113433 VPO C-113434 14x20 AL C-113441 PL C-113443 VPO C-113444</p>
<p>CAUTION</p> <p>DO NOT USE NEAR ELECTRICAL EQUIPMENT</p> <p>3x5 VPO C-113514 7x10 AL C-113521 FG C-113522 PL C-113523 VPO C-113524 10x14 AL C-113531 FG C-113532 PL C-113533 VPO C-113534 14x20 AL C-113541 PL C-113543 VPO C-113544</p>	<p>CAUTION</p> <p>DO NOT USE ON ELECTRICAL FIRES</p> <p>3x5 VPO C-113614 7x10 AL C-113621 FG C-113622 PL C-113623 VPO C-113624 10x14 AL C-113631 FG C-113632 PL C-113633 VPO C-113634 14x20 AL C-113641 PL C-113643 VPO C-113644</p>	<p>CAUTION</p> <p>DO NOT WALK ON CONVEYORS</p> <p>3x5 VPO C-113714 7x10 AL C-113721 FG C-113722 PL C-113723 VPO C-113724 10x14 AL C-113731 FG C-113732 PL C-113733 VPO C-113734 14x20 AL C-113741 PL C-113743 VPO C-113744</p>	<p>CAUTION</p> <p>DO NOT WEAR GLOVES WHILE OPERATING THIS MACHINE</p> <p>3x5 VPO C-113814 7x10 AL C-113821 FG C-113822 PL C-113823 VPO C-113824 10x14 AL C-113831 FG C-113832 PL C-113833 VPO C-113834 14x20 AL C-113841 PL C-113843 VPO C-113844</p>	<p>CAUTION</p> <p>DOCK SLIPPERY WHEN WET</p> <p>3x5 VPO C-113914 7x10 AL C-113921 FG C-113922 PL C-113923 VPO C-113924 10x14 AL C-113931 FG C-113932 PL C-113933 VPO C-113934 14x20 AL C-113941 PL C-113943 VPO C-113944</p>	<p>CAUTION</p> <p>DON'T CLEAN, OIL, OR REPAIR MACHINERY WHILE IN MOTION</p> <p>3x5 VPO C-114014 7x10 AL C-114021 FG C-114022 PL C-114023 VPO C-114024 10x14 AL C-114031 FG C-114032 PL C-114033 VPO C-114034 14x20 AL C-114041 PL C-114043 VPO C-114044</p>	<p>CAUTION</p> <p>DON'T START OUT OF ORDER</p> <p>3x5 VPO C-114214 7x10 AL C-114221 FG C-114222 PL C-114223 VPO C-114224 10x14 AL C-114231 FG C-114232 PL C-114233 VPO C-114234 14x20 AL C-114241 PL C-114243 VPO C-114244</p>
<p>CAUTION</p> <p>DOOR MAY CLOSE SUDDENLY WITHOUT WARNING</p> <p>3x5 VPO C-114314 7x10 AL C-114321 FG C-114322 PL C-114323 VPO C-114324 10x14 AL C-114331 FG C-114332 PL C-114333 VPO C-114334 14x20 AL C-114341 PL C-114343 VPO C-114344</p>	<p>CAUTION</p> <p>DOOR OPENS INWARD</p> <p>3x5 VPO C-114514 7x10 AL C-114521 FG C-114522 PL C-114523 VPO C-114524 10x14 AL C-114531 FG C-114532 PL C-114533 VPO C-114534 14x20 AL C-114541 PL C-114543 VPO C-114544</p>	<p>CAUTION</p> <p>DOOR OPENS OUTWARD</p> <p>3x5 VPO C-114414 7x10 AL C-114421 FG C-114422 PL C-114423 VPO C-114424 10x14 AL C-114431 FG C-114432 PL C-114433 VPO C-114434 14x20 AL C-114441 PL C-114443 VPO C-114444</p>	<p>CAUTION</p> <p>EAR AND EYE PROTECTION AREA</p> <p>3x5 VPO C-160114 7x10 AL C-160121 FG C-160122 PL C-160123 VPO C-160124 10x14 AL C-160131 FG C-160132 PL C-160133 VPO C-160134 14x20 AL C-160141 PL C-160143 VPO C-160144</p>	<p>CAUTION</p> <p>EAR PLUGS REQUIRED IN THIS AREA</p> <p>3x5 VPO C-161214 7x10 AL C-161221 FG C-161222 PL C-161223 VPO C-161224 10x14 AL C-161231 FG C-161232 PL C-161233 VPO C-161234 14x20 AL C-161241 PL C-161243 VPO C-161244</p>	<p>CAUTION</p> <p>EAR PROTECTION AREA</p> <p>3x5 VPO C-160214 7x10 AL C-160221 FG C-160222 PL C-160223 VPO C-160224 10x14 AL C-160231 FG C-160232 PL C-160233 VPO C-160234 14x20 AL C-160241 PL C-160243 VPO C-160244</p>	<p>CAUTION</p> <p>EAR PROTECTION MUST BE WORN IN THIS AREA</p> <p>3x5 VPO C-160414 7x10 AL C-160421 FG C-160422 PL C-160423 VPO C-160424 10x14 AL C-160431 FG C-160432 PL C-160433 VPO C-160434 14x20 AL C-160441 PL C-160443 VPO C-160444</p>

THE SIGNS OF A SAFE INDUSTRY



CAUTION

CAUTION EAR PROTECTION MUST BE WORN WHILE WORKING ON THIS OPERATION 3x5 VPO C-160514 7x10 AL C-160521 FG C-160522 PL C-160523 VPO C-160524 10x14 AL C-160531 FG C-160532 PL C-160533 VPO C-160534 14x20 AL C-160541 PL C-160543 VPO C-160544	CAUTION EAR PROTECTION REQUIRED 3x5 VPO C-160614 7x10 AL C-160621 FG C-160622 PL C-160623 VPO C-160624 10x14 AL C-160631 FG C-160632 PL C-160633 VPO C-160634 14x20 AL C-160641 PL C-160643 VPO C-160644	CAUTION EAR PROTECTION REQUIRED AFTER ____HRS dbA 3x5 VPO C-160714 7x10 AL C-160721 FG C-160722 PL C-160723 VPO C-160724 10x14 AL C-160731 FG C-160732 PL C-160733 VPO C-160734 14x20 AL C-160741 PL C-160743 VPO C-160744	CAUTION EAR PROTECTION REQUIRED IN THIS AREA 3x5 VPO C-160814 7x10 AL C-160821 FG C-160822 PL C-160823 VPO C-160824 10x14 AL C-160831 FG C-160832 PL C-160833 VPO C-160834 14x20 AL C-160841 PL C-160843 VPO C-160844	CAUTION EAR PROTECTION REQUIRED NOISE LEVEL IS ABOVE 85dba 3x5 VPO C-160914 7x10 AL C-160921 FG C-160922 PL C-160923 VPO C-160924 10x14 AL C-160931 FG C-160932 PL C-160933 VPO C-160934 14x20 AL C-160941 PL C-160943 VPO C-160944	CAUTION EAR PROTECTION REQUIRED WHEN THIS EQUIPMENT IS OPERATING 3x5 VPO C-161114 7x10 AL C-161121 FG C-161122 PL C-161123 VPO C-161124 10x14 AL C-161131 FG C-161132 PL C-161133 VPO C-161134 14x20 AL C-161141 PL C-161143 VPO C-161144	CAUTION ELECTRICAL HAZARD 3x5 VPO C-960214 7x10 AL C-960221 FG C-960222 PL C-960223 VPO C-960224 10x14 AL C-960231 FG C-960232 PL C-960233 VPO C-960234 14x20 AL C-960241 PL C-960243 VPO C-960244
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

CAUTION ELECTRICAL SHOCK HAZARD 3x5 VPO C-161314 7x10 AL C-161321 FG C-161322 PL C-161323 VPO C-161324 10x14 AL C-161331 FG C-161332 PL C-161333 VPO C-161334 14x20 AL C-161341 PL C-161343 VPO C-161344	CAUTION EMERGENCY STOP 3x5 VPO C-161414 7x10 AL C-161421 FG C-161422 PL C-161423 VPO C-161424 10x14 AL C-161431 FG C-161432 PL C-161433 VPO C-161434 14x20 AL C-161441 PL C-161443 VPO C-161444	CAUTION EMERGENCY STOP BUTTON 3x5 VPO C-960114 7x10 AL C-960121 FG C-960122 PL C-960123 VPO C-960124 10x14 AL C-960131 FG C-960132 PL C-960133 VPO C-960134 14x20 AL C-960141 PL C-960143 VPO C-960144	CAUTION EMPLOYEES ARE NOT PERMITTED TO REMOVE GUARDS OR OPERATE MACHINE WITHOUT THEM 3x5 VPO C-161514 7x10 AL C-161521 FG C-161522 PL C-161523 VPO C-161524 10x14 AL C-161531 FG C-161532 PL C-161533 VPO C-161534 14x20 AL C-161541 PL C-161543 VPO C-161544	CAUTION ENTRY PROHIBITED WITHOUT PERMIT TEST FOR O2 DEFICIENCY, H2S AND COMBUSTIBLE VAPORS 3x5 VPO C-161614 7x10 AL C-161621 FG C-161622 PL C-161623 VPO C-161624 10x14 AL C-161631 FG C-161632 PL C-161633 VPO C-161634 14x20 AL C-161641 PL C-161643 VPO C-161644	CAUTION EQUIPMENT MAY MOVE AUTOMATICALLY WITHOUT WARNING 3x5 VPO C-161714 7x10 AL C-161721 FG C-161722 PL C-161723 VPO C-161724 10x14 AL C-161731 FG C-161732 PL C-161733 VPO C-161734 14x20 AL C-161741 PL C-161743 VPO C-161744	CAUTION EQUIPMENT REMOTELY CONTROLLED 3x5 VPO C-161814 7x10 AL C-161821 FG C-161822 PL C-161823 VPO C-161824 10x14 AL C-161831 FG C-161832 PL C-161833 VPO C-161834 14x20 AL C-161841 PL C-161843 VPO C-161844
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

CAUTION EQUIPMENT STARTS AUTOMATICALLY 3x5 VPO C-161914 7x10 AL C-161921 FG C-161922 PL C-161923 VPO C-161924 10x14 AL C-161931 FG C-161932 PL C-161933 VPO C-161934 14x20 AL C-161941 PL C-161943 VPO C-161944	CAUTION EYE PROTECTION AND HARD HATS MUST BE WORN IN THIS AREA 3x5 VPO C-162114 7x10 AL C-162121 FG C-162122 PL C-162123 VPO C-162124 10x14 AL C-162131 FG C-162132 PL C-162133 VPO C-162134 14x20 AL C-162141 PL C-162143 VPO C-162144	CAUTION EYE PROTECTION AREA 3x5 VPO C-162214 7x10 AL C-162221 FG C-162222 PL C-162223 VPO C-162224 10x14 AL C-162231 FG C-162232 PL C-162233 VPO C-162234 14x20 AL C-162241 PL C-162243 VPO C-162244	CAUTION EYE PROTECTION AREA CONTACT LENSES NOT ALLOWED 3x5 VPO C-162414 7x10 AL C-162421 FG C-162422 PL C-162423 VPO C-162424 10x14 AL C-162431 FG C-162432 PL C-162433 VPO C-162434 14x20 AL C-162441 PL C-162443 VPO C-162444	CAUTION EYE PROTECTION MUST BE WORN IN THIS AREA 3x5 VPO C-162514 7x10 AL C-162521 FG C-162522 PL C-162523 VPO C-162524 10x14 AL C-162531 FG C-162532 PL C-162533 VPO C-162534 14x20 AL C-162541 PL C-162543 VPO C-162544	CAUTION EYE PROTECTION MUST BE WORN WHEN CLEANING THIS EQUIPMENT 3x5 VPO C-162614 7x10 AL C-162621 FG C-162622 PL C-162623 VPO C-162624 10x14 AL C-162631 FG C-162632 PL C-162633 VPO C-162634 14x20 AL C-162641 PL C-162643 VPO C-162644	CAUTION EYE PROTECTION REQUIRED 3x5 VPO C-162714 7x10 AL C-162721 FG C-162722 PL C-162723 VPO C-162724 10x14 AL C-162731 FG C-162732 PL C-162733 VPO C-162734 14x20 AL C-162741 PL C-162743 VPO C-162744
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

CAUTION EYE PROTECTION REQUIRED BEYOND THIS POINT 3x5 VPO C-162814 7x10 AL C-162821 FG C-162822 PL C-162823 VPO C-162824 10x14 AL C-162831 FG C-162832 PL C-162833 VPO C-162834 14x20 AL C-162841 PL C-162843 VPO C-162844	CAUTION EYE PROTECTION REQUIRED IN THIS AREA 3x5 VPO C-162914 7x10 AL C-162921 FG C-162922 PL C-162923 VPO C-162924 10x14 AL C-162931 FG C-162932 PL C-162933 VPO C-162934 14x20 AL C-162941 PL C-162943 VPO C-162944	CAUTION EYE PROTECTION REQUIRED WHEN EQUIPMENT IS OPERATING 3x5 VPO C-171514 7x10 AL C-171521 FG C-171522 PL C-171523 VPO C-171524 10x14 AL C-171531 FG C-171532 PL C-171533 VPO C-171534 14x20 AL C-171541 PL C-171543 VPO C-171544	CAUTION EYE PROTECTION REQUIRED WHEN USING COMPRESSED AIR 3x5 VPO C-163114 7x10 AL C-163121 FG C-163122 PL C-163123 VPO C-163124 10x14 AL C-163131 FG C-163132 PL C-163133 VPO C-163134 14x20 AL C-163141 PL C-163143 VPO C-163144	CAUTION EYE PROTECTION REQUIRED WHILE USING THIS MACHINE 3x5 VPO C-163214 7x10 AL C-163221 FG C-163222 PL C-163223 VPO C-163224 10x14 AL C-163231 FG C-163232 PL C-163233 VPO C-163234 14x20 AL C-163241 PL C-163243 VPO C-163244	CAUTION EYE PROTECTION, GLOVES, APRONS MUST BE WORN WHEN HANDLING CHEMICALS 3x5 VPO C-163314 7x10 AL C-163321 FG C-163322 PL C-163323 VPO C-163324 10x14 AL C-163331 FG C-163332 PL C-163333 VPO C-163334 14x20 AL C-163341 PL C-163343 VPO C-163344	CAUTION FACE LADDER WHEN DESCENDING 3x5 VPO C-260114 7x10 AL C-260121 FG C-260122 PL C-260123 VPO C-260124 10x14 AL C-260131 FG C-260132 PL C-260133 VPO C-260134 14x20 AL C-260141 PL C-260143 VPO C-260144
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

CAUTION

THE SIGNS OF A SAFE INDUSTRY



CAUTION
FACE MASK
MUST BE WORN
IN SPRAY BOOTH

3x5 VPO C-261814
7x10 AL C-261821
FG C-261822
PL C-261823
VPO C-261824
10x14 AL C-261831
FG C-261832
PL C-261833
VPO C-261834
14x20 AL C-261841
PL C-261843
VPO C-261844

CAUTION
FACE SHIELD AND
GLOVES REQUIRED
WHEN USING
THIS EQUIPMENT

3x5 VPO C-260314
7x10 AL C-260321
FG C-260322
PL C-260323
VPO C-260324
10x14 AL C-260331
FG C-260332
PL C-260333
VPO C-260334
14x20 AL C-260341
PL C-260343
VPO C-260344

CAUTION
FACE SHIELD AND
GOGGLES
MUST BE WORN
IN THIS AREA

3x5 VPO C-260414
7x10 AL C-260421
FG C-260422
PL C-260423
VPO C-260424
10x14 AL C-260431
FG C-260432
PL C-260433
VPO C-260434
14x20 AL C-260441
PL C-260443
VPO C-260444

CAUTION
FACE SHIELD AND
GOGGLES MUST BE
WORN WHEN USING
THIS MACHINE

3x5 VPO C-260514
7x10 AL C-260521
FG C-260522
PL C-260523
VPO C-260524
10x14 AL C-260531
FG C-260532
PL C-260533
VPO C-260534
14x20 AL C-260541
PL C-260543
VPO C-260544

CAUTION
FACE
SHIELD
AREA

3x5 VPO C-260614
7x10 AL C-260621
FG C-260622
PL C-260623
VPO C-260624
10x14 AL C-260631
FG C-260632
PL C-260633
VPO C-260634
14x20 AL C-260641
PL C-260643
VPO C-260644

CAUTION
FACE SHIELD APRON
AND RUBBER GLOVES
REQUIRED WHEN
HANDLING BATTERIES
AND ADDING WATER

3x5 VPO C-260714
7x10 AL C-260721
FG C-260722
PL C-260723
VPO C-260724
10x14 AL C-260731
FG C-260732
PL C-260733
VPO C-260734
14x20 AL C-260741
PL C-260743
VPO C-260744

CAUTION
FALL
PROTECTION
REQUIRED

3x5 VPO C-981114
7x10 AL C-981121
FG C-981122
PL C-981123
VPO C-981124
10x14 AL C-981131
FG C-981132
PL C-981133
VPO C-981134
14x20 AL C-981141
PL C-981143
VPO C-981144

CAUTION
FIRE LANE
KEEP CLEAR

3x5 VPO C-260914
7x10 AL C-260921
FG C-260922
PL C-260923
VPO C-260924
10x14 AL C-260931
FG C-260932
PL C-260933
VPO C-260934
14x20 AL C-260941
PL C-260943
VPO C-260944

CAUTION
FLAMMABLE

3x5 VPO C-960414
7x10 AL C-960421
FG C-960422
PL C-960423
VPO C-960424
10x14 AL C-960431
FG C-960432
PL C-960433
VPO C-960434
14x20 AL C-960441
PL C-960443
VPO C-960444

CAUTION
FLAMMABLE
VAPORS

3x5 VPO C-261114
7x10 AL C-261121
FG C-261122
PL C-261123
VPO C-261124
10x14 AL C-261131
FG C-261132
PL C-261133
VPO C-261134
14x20 AL C-261141
PL C-261143
VPO C-261144

CAUTION
FLOOR LOAD

LBS.
PER SQUARE FOOT

3x5 VPO C-261214
7x10 AL C-261221
FG C-261222
PL C-261223
VPO C-261224
10x14 AL C-261231
FG C-261232
PL C-261233
VPO C-261234
14x20 AL C-261241
PL C-261243
VPO C-261244

CAUTION
FOOT PROTECTION
REQUIRED
IN THIS AREA

3x5 VPO C-261314
7x10 AL C-261321
FG C-261322
PL C-261323
VPO C-261324
10x14 AL C-261331
FG C-261332
PL C-261333
VPO C-261334
14x20 AL C-261341
PL C-261343
VPO C-261344

CAUTION
GLOVES AND
GOGGLES REQUIRED
WHEN FILLING TANKS

3x5 VPO C-360114
7x10 AL C-360121
FG C-360122
PL C-360123
VPO C-360124
10x14 AL C-360131
FG C-360132
PL C-360133
VPO C-360134
14x20 AL C-360141
PL C-360143
VPO C-360144

CAUTION
GLOVES AND
GOGGLES POSITIVELY
MUST BE WORN

3x5 VPO C-960514
7x10 AL C-960521
FG C-960522
PL C-960523
VPO C-960524
10x14 AL C-960531
FG C-960532
PL C-960533
VPO C-960534
14x20 AL C-960541
PL C-960543
VPO C-960544

CAUTION
GOGGLES
POSITIVELY
MUST BE WORN

3x5 VPO C-360214
7x10 AL C-360221
FG C-360222
PL C-360223
VPO C-360224
10x14 AL C-360231
FG C-360232
PL C-360233
VPO C-360234
14x20 AL C-360241
PL C-360243
VPO C-360244

CAUTION
GOGGLES POSITIVELY
MUST BE WORN
WHEN OPERATING
THIS MACHINE

3x5 VPO C-360414
7x10 AL C-360421
FG C-360422
PL C-360423
VPO C-360424
10x14 AL C-360431
FG C-360432
PL C-360433
VPO C-360434
14x20 AL C-360441
PL C-360443
VPO C-360444

CAUTION
GROUND ALL
BARRELS

3x5 VPO C-360514
7x10 AL C-360521
FG C-360522
PL C-360523
VPO C-360524
10x14 AL C-360531
FG C-360532
PL C-360533
VPO C-360534
14x20 AL C-360541
PL C-360543
VPO C-360544

CAUTION
GROUND
BARRELS
BEFORE USING

3x5 VPO C-360614
7x10 AL C-360621
FG C-360622
PL C-360623
VPO C-360624
10x14 AL C-360631
FG C-360632
PL C-360633
VPO C-360634
14x20 AL C-360641
PL C-360643
VPO C-360644

CAUTION
H₂S
MAY BE PRESENT
DO NOT ENTER THIS AREA
WITHOUT APPROVED H₂S
DETECTION EQUIPMENT

3x5 VPO C-370114
7x10 AL C-370121
FG C-370122
PL C-370123
VPO C-370124
10x14 AL C-370131
FG C-370132
PL C-370133
VPO C-370134
14x20 AL C-370141
PL C-370143
VPO C-370144

CAUTION
H₂S
POISONOUS GAS
MAY BE PRESENT

3x5 VPO C-370214
7x10 AL C-370221
FG C-370222
PL C-370223
VPO C-370224
10x14 AL C-370231
FG C-370232
PL C-370233
VPO C-370234
14x20 AL C-370241
PL C-370243
VPO C-370244

CAUTION
HARD HAT
AREA

3x5 VPO C-370314
7x10 AL C-370321
FG C-370322
PL C-370323
VPO C-370324
10x14 AL C-370331
FG C-370332
PL C-370333
VPO C-370334
14x20 AL C-370341
PL C-370343
VPO C-370344

CAUTION
HARD HAT
REQUIRED

3x5 VPO C-960314
7x10 AL C-960321
FG C-960322
PL C-960323
VPO C-960324
10x14 AL C-960331
FG C-960332
PL C-960333
VPO C-960334
14x20 AL C-960341
PL C-960343
VPO C-960344

CAUTION
HARD HATS AND
EYE PROTECTION
MUST BE WORN
IN THIS AREA

3x5 VPO C-370514
7x10 AL C-370521
FG C-370522
PL C-370523
VPO C-370524
10x14 AL C-370531
FG C-370532
PL C-370533
VPO C-370534
14x20 AL C-370541
PL C-370543
VPO C-370544

CAUTION
HARD HATS AND
EYE PROTECTION
REQUIRED

3x5 VPO C-370614
7x10 AL C-370621
FG C-370622
PL C-370623
VPO C-370624
10x14 AL C-370631
FG C-370632
PL C-370633
VPO C-370634
14x20 AL C-370641
PL C-370643
VPO C-370644

CAUTION
HARD HATS
MUST BE WORN
IN THIS AREA

3x5 VPO C-370714
7x10 AL C-370721
FG C-370722
PL C-370723
VPO C-370724
10x14 AL C-370731
FG C-370732
PL C-370733
VPO C-370734
14x20 AL C-370741
PL C-370743
VPO C-370744

CAUTION
HARD HATS
REQUIRED

3x5 VPO C-370814
7x10 AL C-370821
FG C-370822
PL C-370823
VPO C-370824
10x14 AL C-370831
FG C-370832
PL C-370833
VPO C-370834
14x20 AL C-370841
PL C-370843
VPO C-370844

CAUTION
HARD HATS
REQUIRED
IN THIS AREA

3x5 VPO C-960614
7x10 AL C-960621
FG C-960622
PL C-960623
VPO C-960624
10x14 AL C-960631
FG C-960632
PL C-960633
VPO C-960634
14x20 AL C-960641
PL C-960643
VPO C-960644

CAUTION
HARD HATS,
EYE PROTECTION,
EAR PROTECTION
MUST BE WORN
BEYOND THIS POINT

3x5 VPO C-371014
7x10 AL C-371021
FG C-371022
PL C-371023
VPO C-371024
10x14 AL C-371031
FG C-371032
PL C-371033
VPO C-371034
14x20 AL C-371041
PL C-371043
VPO C-371044