



3x5 VPO D-162414
7x10 AL D-162421
FG D-162422
PL D-162423
VPO D-162424
10x14 AL D-162431
FG D-162432
PL D-162433
VPO D-162434
14x20 AL D-162441
PL D-162443
VPO D-162444



3x5 VPO D-162514
7x10 AL D-162521
FG D-162522
PL D-162523
VPO D-162524
10x14 AL D-162531
FG D-162532
PL D-162533
VPO D-162534
14x20 AL D-162541
PL D-162543
VPO D-162544



3x5 VPO D-162614
7x10 AL D-162621
FG D-162622
PL D-162623
VPO D-162624
10x14 AL D-162631
FG D-162632
PL D-162633
VPO D-162634
14x20 AL D-162641
PL D-162643
VPO D-162644



3x5 VPO D-162814
7x10 AL D-162821
FG D-162822
PL D-162823
VPO D-162824
10x14 AL D-162831
FG D-162832
PL D-162833
VPO D-162834
14x20 AL D-162841
PL D-162843
VPO D-162844



3x5 VPO D-162914
7x10 AL D-162921
FG D-162922
PL D-162923
VPO D-162924
10x14 AL D-162931
FG D-162932
PL D-162933
VPO D-162934
14x20 AL D-162941
PL D-162943
VPO D-162944



3x5 VPO D-163014
7x10 AL D-163021
FG D-163022
PL D-163023
VPO D-163024
10x14 AL D-163031
FG D-163032
PL D-163033
VPO D-163034
14x20 AL D-163041
PL D-163043
VPO D-163044



3x5 VPO D-874314
7x10 AL D-874321
FG D-874322
PL D-874323
VPO D-874324
10x14 AL D-874331
FG D-874332
PL D-874333
VPO D-874334
14x20 AL D-874341
PL D-874343
VPO D-874344



3x5 VPO D-163114
7x10 AL D-163121
FG D-163122
PL D-163123
VPO D-163124
10x14 AL D-163131
FG D-163132
PL D-163133
VPO D-163134
14x20 AL D-163141
PL D-163143
VPO D-163144



3x5 VPO D-260114
7x10 AL D-260121
FG D-260122
PL D-260123
VPO D-260124
10x14 AL D-260131
FG D-260132
PL D-260133
VPO D-260134
14x20 AL D-260141
PL D-260143
VPO D-260144



3x5 VPO D-260214
7x10 AL D-260221
FG D-260222
PL D-260223
VPO D-260224
10x14 AL D-260231
FG D-260232
PL D-260233
VPO D-260234
14x20 AL D-260241
PL D-260243
VPO D-260244



3x5 VPO D-874214
7x10 AL D-874221
FG D-874222
PL D-874223
VPO D-874224
10x14 AL D-874231
FG D-874232
PL D-874233
VPO D-874234
14x20 AL D-874241
PL D-874243
VPO D-874244



3x5 VPO D-260414
7x10 AL D-260421
FG D-260422
PL D-260423
VPO D-260424
10x14 AL D-260431
FG D-260432
PL D-260433
VPO D-260434
14x20 AL D-260441
PL D-260443
VPO D-260444



3x5 VPO D-260614
7x10 AL D-260621
FG D-260622
PL D-260623
VPO D-260624
10x14 AL D-260631
FG D-260632
PL D-260633
VPO D-260634
14x20 AL D-260641
PL D-260643
VPO D-260644



3x5 VPO D-260714
7x10 AL D-260721
FG D-260722
PL D-260723
VPO D-260724
10x14 AL D-260731
FG D-260732
PL D-260733
VPO D-260734
14x20 AL D-260741
PL D-260743
VPO D-260744



3x5 VPO D-260814
7x10 AL D-260821
FG D-260822
PL D-260823
VPO D-260824
10x14 AL D-260831
FG D-260832
PL D-260833
VPO D-260834
14x20 AL D-260841
PL D-260843
VPO D-260844



3x5 VPO D-260914
7x10 AL D-260921
FG D-260922
PL D-260923
VPO D-260924
10x14 AL D-260931
FG D-260932
PL D-260933
VPO D-260934
14x20 AL D-260941
PL D-260943
VPO D-260944



3x5 VPO D-962514
7x10 AL D-962521
FG D-962522
PL D-962523
VPO D-962524
10x14 AL D-962531
FG D-962532
PL D-962533
VPO D-962534
14x20 AL D-962541
PL D-962543
VPO D-962544



3x5 VPO D-261014
7x10 AL D-261021
FG D-261022
PL D-261023
VPO D-261024
10x14 AL D-261031
FG D-261032
PL D-261033
VPO D-261034
14x20 AL D-261041
PL D-261043
VPO D-261044



3x5 VPO D-261114
7x10 AL D-261121
FG D-261122
PL D-261123
VPO D-261124
10x14 AL D-261131
FG D-261132
PL D-261133
VPO D-261134
14x20 AL D-261141
PL D-261143
VPO D-261144



3x5 VPO D-261214
7x10 AL D-261221
FG D-261222
PL D-261223
VPO D-261224
10x14 AL D-261231
FG D-261232
PL D-261233
VPO D-261234
14x20 AL D-261241
PL D-261243
VPO D-261244



3x5 VPO D-261314
7x10 AL D-261321
FG D-261322
PL D-261323
VPO D-261324
10x14 AL D-261331
FG D-261332
PL D-261333
VPO D-261334
14x20 AL D-261341
PL D-261343
VPO D-261344



3x5 VPO D-261414
7x10 AL D-261421
FG D-261422
PL D-261423
VPO D-261424
10x14 AL D-261431
FG D-261432
PL D-261433
VPO D-261434
14x20 AL D-261441
PL D-261443
VPO D-261444



3x5 VPO D-261514
7x10 AL D-261521
FG D-261522
PL D-261523
VPO D-261524
10x14 AL D-261531
FG D-261532
PL D-261533
VPO D-261534
14x20 AL D-261541
PL D-261543
VPO D-261544



3x5 VPO D-261614
7x10 AL D-261621
FG D-261622
PL D-261623
VPO D-261624
10x14 AL D-261631
FG D-261632
PL D-261633
VPO D-261634
14x20 AL D-261641
PL D-261643
VPO D-261644



3x5 VPO D-261714
7x10 AL D-261721
FG D-261722
PL D-261723
VPO D-261724
10x14 AL D-261731
FG D-261732
PL D-261733
VPO D-261734
14x20 AL D-261741
PL D-261743
VPO D-261744



3x5 VPO D-360114
7x10 AL D-360121
FG D-360122
PL D-360123
VPO D-360124
10x14 AL D-360131
FG D-360132
PL D-360133
VPO D-360134
14x20 AL D-360141
PL D-360143
VPO D-360144



3x5 VPO D-360214
7x10 AL D-360221
FG D-360222
PL D-360223
VPO D-360224
10x14 AL D-360231
FG D-360232
PL D-360233
VPO D-360234
14x20 AL D-360241
PL D-360243
VPO D-360244



3x5 VPO D-360314
7x10 AL D-360321
FG D-360322
PL D-360323
VPO D-360324
10x14 AL D-360331
FG D-360332
PL D-360333
VPO D-360334
14x20 AL D-360341
PL D-360343
VPO D-360344

THE SIGNS OF A SAFE INDUSTRY

MATERIALS



DANGER
GO SLOW

3x5 VPO D-360414
7x10 AL D-360421
FG D-360422
PL D-360423
VPO D-360424
10x14 AL D-360431
FG D-360432
PL D-360433
VPO D-360434
14x20 AL D-360441
PL D-360443
VPO D-360444

DANGER
GO SLOW
SOUND HORN

3x5 VPO D-360514
7x10 AL D-360521
FG D-360522
PL D-360523
VPO D-360524
10x14 AL D-360531
FG D-360532
PL D-360533
VPO D-360534
14x20 AL D-360541
PL D-360543
VPO D-360544

DANGER
GOGGLES
MUST BE WORN
WHEN USING AIR HOSES

3x5 VPO D-360714
7x10 AL D-360721
FG D-360722
PL D-360723
VPO D-360724
10x14 AL D-360731
FG D-360732
PL D-360733
VPO D-360734
14x20 AL D-360741
PL D-360743
VPO D-360744

DANGER
GOGGLES
OR FACE SHIELD
MUST BE WORN
IN THIS AREA

3x5 VPO D-360814
7x10 AL D-360821
FG D-360822
PL D-360823
VPO D-360824
10x14 AL D-360831
FG D-360832
PL D-360833
VPO D-360834
14x20 AL D-360841
PL D-360843
VPO D-360844

DANGER
GUARD DOGS
ON DUTY

3x5 VPO D-360914
7x10 AL D-360921
FG D-360922
PL D-360923
VPO D-360924
10x14 AL D-360931
FG D-360932
PL D-360933
VPO D-360934
14x20 AL D-360941
PL D-360943
VPO D-360944

DANGER
H₂S MAY
BE PRESENT

3x5 VPO D-370214
7x10 AL D-370221
FG D-370222
PL D-370223
VPO D-370224
10x14 AL D-370231
FG D-370232
PL D-370233
VPO D-370234
14x20 AL D-370241
PL D-370243
VPO D-370244

DANGER
H₂S
POISONOUS GAS

3x5 VPO D-370314
7x10 AL D-370321
FG D-370322
PL D-370323
VPO D-370324
10x14 AL D-370331
FG D-370332
PL D-370333
VPO D-370334
14x20 AL D-370341
PL D-370343
VPO D-370344

DANGER
HAND HAZARD

3x5 VPO D-962614
7x10 AL D-962621
FG D-962622
PL D-962623
VPO D-962624
10x14 AL D-962631
FG D-962632
PL D-962633
VPO D-962634
14x20 AL D-962641
PL D-962643
VPO D-962644

DANGER
HAND HAZARD
TURN POWER OFF
BEFORE REACHING IN

3x5 VPO D-370414
7x10 AL D-370421
FG D-370422
PL D-370423
VPO D-370424
10x14 AL D-370431
FG D-370432
PL D-370433
VPO D-370434
14x20 AL D-370441
PL D-370443
VPO D-370444

DANGER
HAND HAZARD
WATCH
YOUR FINGERS

3x5 VPO D-370514
7x10 AL D-370521
FG D-370522
PL D-370523
VPO D-370524
10x14 AL D-370531
FG D-370532
PL D-370533
VPO D-370534
14x20 AL D-370541
PL D-370543
VPO D-370544

DANGER
HANDS OFF

3x5 VPO D-370614
7x10 AL D-370621
FG D-370622
PL D-370623
VPO D-370624
10x14 AL D-370631
FG D-370632
PL D-370633
VPO D-370634
14x20 AL D-370641
PL D-370643
VPO D-370644

DANGER
HARD HAT
AND EYE PROTECTION
MUST BE WORN
IN THIS AREA

3x5 VPO D-370714
7x10 AL D-370721
FG D-370722
PL D-370723
VPO D-370724
10x14 AL D-370731
FG D-370732
PL D-370733
VPO D-370734
14x20 AL D-370741
PL D-370743
VPO D-370744

DANGER
HARD HAT
AREA

3x5 VPO D-370814
7x10 AL D-370821
FG D-370822
PL D-370823
VPO D-370824
10x14 AL D-370831
FG D-370832
PL D-370833
VPO D-370834
14x20 AL D-370841
PL D-370843
VPO D-370844

DANGER
HARD HATS AND
SAFETY GLASSES
REQUIRED

3x5 VPO D-370914
7x10 AL D-370921
FG D-370922
PL D-370923
VPO D-370924
10x14 AL D-370931
FG D-370932
PL D-370933
VPO D-370934
14x20 AL D-370941
PL D-370943
VPO D-370944

DANGER
HARD HAT
PROTECTION
REQUIRED

3x5 VPO D-371014
7x10 AL D-371021
FG D-371022
PL D-371023
VPO D-371024
10x14 AL D-371031
FG D-371032
PL D-371033
VPO D-371034
14x20 AL D-371041
PL D-371043
VPO D-371044

DANGER
HARD HAT
REQUIRED
BEYOND THIS POINT

3x5 VPO D-922914
7x10 AL D-922921
FG D-922922
PL D-922923
VPO D-922924
10x14 AL D-922931
FG D-922932
PL D-922933
VPO D-922934
14x20 AL D-922941
PL D-922943
VPO D-922944

DANGER
HARD HAT
STEEL TOE SHOES
& SAFETY GLASSES
REQUIRED
BEYOND THIS POINT

3x5 VPO D-923114
7x10 AL D-923121
FG D-923122
PL D-923123
VPO D-923124
10x14 AL D-923131
FG D-923132
PL D-923133
VPO D-923134
14x20 AL D-923141
PL D-923143
VPO D-923144

DANGER
HAZARDOUS
AREA

3x5 VPO D-371114
7x10 AL D-371121
FG D-371122
PL D-371123
VPO D-371124
10x14 AL D-371131
FG D-371132
PL D-371133
VPO D-371134
14x20 AL D-371141
PL D-371143
VPO D-371144

DANGER
HAZARDOUS AREA
AUTHORIZED
PERSONNEL ONLY

3x5 VPO D-371214
7x10 AL D-371221
FG D-371222
PL D-371223
VPO D-371224
10x14 AL D-371231
FG D-371232
PL D-371233
VPO D-371234
14x20 AL D-371241
PL D-371243
VPO D-371244

DANGER
HAZARDOUS
CHEMICALS

3x5 VPO D-371314
7x10 AL D-371321
FG D-371322
PL D-371323
VPO D-371324
10x14 AL D-371331
FG D-371332
PL D-371333
VPO D-371334
14x20 AL D-371341
PL D-371343
VPO D-371344

DANGER
HAZARDOUS MATERIAL
STORAGE AREA
UNAUTHORIZED PERSONNEL
KEEP CLEAR

3x5 VPO D-371514
7x10 AL D-371521
FG D-371522
PL D-371523
VPO D-371524
10x14 AL D-371531
FG D-371532
PL D-371533
VPO D-371534
14x20 AL D-371541
PL D-371543
VPO D-371544

DANGER
HAZARDOUS
MATERIALS

3x5 VPO D-371614
7x10 AL D-371621
FG D-371622
PL D-371623
VPO D-371624
10x14 AL D-371631
FG D-371632
PL D-371633
VPO D-371634
14x20 AL D-371641
PL D-371643
VPO D-371644

DANGER
HAZARDOUS WASTE
AUTHORIZED
PERSONNEL ONLY

3x5 VPO D-371714
7x10 AL D-371721
FG D-371722
PL D-371723
VPO D-371724
10x14 AL D-371731
FG D-371732
PL D-371733
VPO D-371734
14x20 AL D-371741
PL D-371743
VPO D-371744

DANGER
HAZARDOUS
WASTE STORAGE

3x5 VPO D-371814
7x10 AL D-371821
FG D-371822
PL D-371823
VPO D-371824
10x14 AL D-371831
FG D-371832
PL D-371833
VPO D-371834
14x20 AL D-371841
PL D-371843
VPO D-371844

DANGER
HAZARDOUS WASTE
STORAGE AREA
UNAUTHORIZED PERSONS
KEEP OUT

3x5 VPO D-371914
7x10 AL D-371921
FG D-371922
PL D-371923
VPO D-371924
10x14 AL D-371931
FG D-371932
PL D-371933
VPO D-371934
14x20 AL D-371941
PL D-371943
VPO D-371944

DANGER
HAZARDOUS WASTE
STORAGE FLAMMABLE
NO SMOKING

3x5 VPO D-372014
7x10 AL D-372021
FG D-372022
PL D-372023
VPO D-372024
10x14 AL D-372031
FG D-372032
PL D-372033
VPO D-372034
14x20 AL D-372041
PL D-372043
VPO D-372044

DANGER
HAZARDOUS WASTE
TREATMENT AREA
UNAUTHORIZED PERSONS
KEEP OUT

3x5 VPO D-372114
7x10 AL D-372121
FG D-372122
PL D-372123
VPO D-372124
10x14 AL D-372131
FG D-372132
PL D-372133
VPO D-372134
14x20 AL D-372141
PL D-372143
VPO D-372144

DANGER
HAZARDOUS WASTE
UNAUTHORIZED PERSONNEL
KEEP OUT

3x5 VPO D-372214
7x10 AL D-372221
FG D-372222
PL D-372223
VPO D-372224
10x14 AL D-372231
FG D-372232
PL D-372233
VPO D-372234
14x20 AL D-372241
PL D-372243
VPO D-372244

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!



DANGER HIGH PRESSURE GAS LINE	DANGER HIGH PRESSURE PIPE LINE	DANGER HIGH VOLTAGE	DANGER HIGH VOLTAGE 440 VOLTS	DANGER HIGH VOLTAGE ABOVE	DANGER HIGH VOLTAGE AUTHORIZED PERSONNEL ONLY	DANGER HIGH VOLTAGE CABLE BURIED HERE
3x5 VPO D-372414 7x10 AL D-372421 FG D-372422 PL D-372423 VPO D-372424 10x14 AL D-372431 FG D-372432 PL D-372433 VPO D-372434 14x20 AL D-372441 PL D-372443 VPO D-372444	3x5 VPO D-372514 7x10 AL D-372521 FG D-372522 PL D-372523 VPO D-372524 10x14 AL D-372531 FG D-372532 PL D-372533 VPO D-372534 14x20 AL D-372541 PL D-372543 VPO D-372544	3x5 VPO D-372614 7x10 AL D-372621 FG D-372622 PL D-372623 VPO D-372624 10x14 AL D-372631 FG D-372632 PL D-372633 VPO D-372634 14x20 AL D-372641 PL D-372643 VPO D-372644	3x5 VPO D-372914 7x10 AL D-372921 FG D-372922 PL D-372923 VPO D-372924 10x14 AL D-372931 FG D-372932 PL D-372933 VPO D-372934 14x20 AL D-372941 PL D-372943 VPO D-372944	3x5 VPO D-373114 7x10 AL D-373121 FG D-373122 PL D-373123 VPO D-373124 10x14 AL D-373131 FG D-373132 PL D-373133 VPO D-373134 14x20 AL D-373141 PL D-373143 VPO D-373144	3x5 VPO D-373214 7x10 AL D-373221 FG D-373222 PL D-373223 VPO D-373224 10x14 AL D-373231 FG D-373232 PL D-373233 VPO D-373234 14x20 AL D-373241 PL D-373243 VPO D-373244	3x5 VPO D-373314 7x10 AL D-373321 FG D-373322 PL D-373323 VPO D-373324 10x14 AL D-373331 FG D-373332 PL D-373333 VPO D-373334 14x20 AL D-373341 PL D-373343 VPO D-373344

DANGER HIGH VOLTAGE ELECTRICAL EQUIPMENT	DANGER HIGH VOLTAGE KEEP AWAY	DANGER HIGH VOLTAGE KEEP OUT	DANGER HIGH VOLTAGE LINES OVERHEAD	DANGER HIGH VOLTAGE NO ENTRY	DANGER HIGH VOLTAGE NO TRESPASSING	DANGER HIGH VOLTAGE OVERHEAD WIRES
3x5 VPO D-373414 7x10 AL D-373421 FG D-373422 PL D-373423 VPO D-373424 10x14 AL D-373431 FG D-373432 PL D-373433 VPO D-373434 14x20 AL D-373441 PL D-373443 VPO D-373444	3x5 VPO D-373614 7x10 AL D-373621 FG D-373622 PL D-373623 VPO D-373624 10x14 AL D-373631 FG D-373632 PL D-373633 VPO D-373634 14x20 AL D-373641 PL D-373643 VPO D-373644	3x5 VPO D-373914 7x10 AL D-373921 FG D-373922 PL D-373923 VPO D-373924 10x14 AL D-373931 FG D-373932 PL D-373933 VPO D-373934 14x20 AL D-373941 PL D-373943 VPO D-373944	3x5 VPO D-374014 7x10 AL D-374021 FG D-374022 PL D-374023 VPO D-374024 10x14 AL D-374031 FG D-374032 PL D-374033 VPO D-374034 14x20 AL D-374041 PL D-374043 VPO D-374044	3x5 VPO D-374114 7x10 AL D-374121 FG D-374122 PL D-374123 VPO D-374124 10x14 AL D-374131 FG D-374132 PL D-374133 VPO D-374134 14x20 AL D-374141 PL D-374143 VPO D-374144	3x5 VPO D-374214 7x10 AL D-374221 FG D-374222 PL D-374223 VPO D-374224 10x14 AL D-374231 FG D-374232 PL D-374233 VPO D-374234 14x20 AL D-374241 PL D-374243 VPO D-374244	3x5 VPO D-374314 7x10 AL D-374321 FG D-374322 PL D-374323 VPO D-374324 10x14 AL D-374331 FG D-374332 PL D-374333 VPO D-374334 14x20 AL D-374341 PL D-374343 VPO D-374344

DANGER HIGH VOLTAGE RESTRICTED AREA AUTHORIZED PERSONNEL ONLY	DANGER HIGH VOLTAGE UNAUTHORIZED PERSONNEL KEEP OUT	DANGER HIGH VOLTAGE UNAUTHORIZED PERSONS KEEP OUT	DANGER HIGH-HAZARD CONFINED SPACE PERMIT AND SAFETY ATTENDANT REQUIRED	DANGER HIGHLY COMBUSTIBLE AREA NO BURNING, WELDING OR OPEN FLAME PERMITTED	DANGER HIGHLY FLAMMABLE	DANGER HOT
3x5 VPO D-374514 7x10 AL D-374521 FG D-374522 PL D-374523 VPO D-374524 10x14 AL D-374531 FG D-374532 PL D-374533 VPO D-374534 14x20 AL D-374541 PL D-374543 VPO D-374544	3x5 VPO D-374614 7x10 AL D-374621 FG D-374622 PL D-374623 VPO D-374624 10x14 AL D-374631 FG D-374632 PL D-374633 VPO D-374634 14x20 AL D-374641 PL D-374643 VPO D-374644	3x5 VPO D-374714 7x10 AL D-374721 FG D-374722 PL D-374723 VPO D-374724 10x14 AL D-374731 FG D-374732 PL D-374733 VPO D-374734 14x20 AL D-374741 PL D-374743 VPO D-374744	3x5 VPO D-376814 7x10 AL D-376821 FG D-376822 PL D-376823 VPO D-376824 10x14 AL D-376831 FG D-376832 PL D-376833 VPO D-376834 14x20 AL D-376841 PL D-376843 VPO D-376844	3x5 VPO D-374914 7x10 AL D-374921 FG D-374922 PL D-374923 VPO D-374924 10x14 AL D-374931 FG D-374932 PL D-374933 VPO D-374934 14x20 AL D-374941 PL D-374943 VPO D-374944	3x5 VPO D-375014 7x10 AL D-375021 FG D-375022 PL D-375023 VPO D-375024 10x14 AL D-375031 FG D-375032 PL D-375033 VPO D-375034 14x20 AL D-375041 PL D-375043 VPO D-375044	3x5 VPO D-375214 7x10 AL D-375221 FG D-375222 PL D-375223 VPO D-375224 10x14 AL D-375231 FG D-375232 PL D-375233 VPO D-375234 14x20 AL D-375241 PL D-375243 VPO D-375244

DANGER HOT EQUIPMENT UNAUTHORIZED PERSONS KEEP OUT	DANGER HOT METAL	DANGER HOT PIPES	DANGER HOT STEAM	DANGER HOT STEAM PIPES	DANGER HOT SURFACE	DANGER HOT SURFACES
3x5 VPO D-375314 7x10 AL D-375321 FG D-375322 PL D-375323 VPO D-375324 10x14 AL D-375331 FG D-375332 PL D-375333 VPO D-375334 14x20 AL D-375341 PL D-375343 VPO D-375344	3x5 VPO D-375414 7x10 AL D-375421 FG D-375422 PL D-375423 VPO D-375424 10x14 AL D-375431 FG D-375432 PL D-375433 VPO D-375434 14x20 AL D-375441 PL D-375443 VPO D-375444	3x5 VPO D-375614 7x10 AL D-375621 FG D-375622 PL D-375623 VPO D-375624 10x14 AL D-375631 FG D-375632 PL D-375633 VPO D-375634 14x20 AL D-375641 PL D-375643 VPO D-375644	3x5 VPO D-375714 7x10 AL D-375721 FG D-375722 PL D-375723 VPO D-375724 10x14 AL D-375731 FG D-375732 PL D-375733 VPO D-375734 14x20 AL D-375741 PL D-375743 VPO D-375744	3x5 VPO D-375814 7x10 AL D-375821 FG D-375822 PL D-375823 VPO D-375824 10x14 AL D-375831 FG D-375832 PL D-375833 VPO D-375834 14x20 AL D-375841 PL D-375843 VPO D-375844	3x5 VPO D-375914 7x10 AL D-375921 FG D-375922 PL D-375923 VPO D-375924 10x14 AL D-375931 FG D-375932 PL D-375933 VPO D-375934 14x20 AL D-375941 PL D-375943 VPO D-375944	3x5 VPO D-376014 7x10 AL D-376021 FG D-376022 PL D-376023 VPO D-376024 10x14 AL D-376031 FG D-376032 PL D-376033 VPO D-376034 14x20 AL D-376041 PL D-376043 VPO D-376044

THE SIGNS OF A SAFE INDUSTRY



DANGER
HYDROCHLORIC ACID

3x5 VPO D-376214
7x10 AL D-376221
FG D-376222
PL D-376223
VPO D-376224
10x14 AL D-376231
FG D-376232
PL D-376233
VPO D-376234
14x20 AL D-376241
PL D-376243
VPO D-376244

DANGER
HYDROGEN

3x5 VPO D-376414
7x10 AL D-376421
FG D-376422
PL D-376423
VPO D-376424
10x14 AL D-376431
FG D-376432
PL D-376433
VPO D-376434
14x20 AL D-376441
PL D-376443
VPO D-376444

DANGER
HYDROGEN PEROXIDE

3x5 VPO D-376514
7x10 AL D-376521
FG D-376522
PL D-376523
VPO D-376524
10x14 AL D-376531
FG D-376532
PL D-376533
VPO D-376534
14x20 AL D-376541
PL D-376543
VPO D-376544

DANGER
HYDROGEN SULFIDE

3x5 VPO D-376614
7x10 AL D-376621
FG D-376622
PL D-376623
VPO D-376624
10x14 AL D-376631
FG D-376632
PL D-376633
VPO D-376634
14x20 AL D-376641
PL D-376643
VPO D-376644

DANGER
HYDROGEN SULFIDE GAS

3x5 VPO D-376714
7x10 AL D-376721
FG D-376722
PL D-376723
VPO D-376724
10x14 AL D-376731
FG D-376732
PL D-376733
VPO D-376734
14x20 AL D-376741
PL D-376743
VPO D-376744

DANGER
INORGANIC ARSENIC
CANCER HAZARD
AUTHORIZED PERSONNEL ONLY
NO SMOKING OR EATING
RESPIRATOR REQUIRED

3x5 VPO D-420214
7x10 AL D-420221
FG D-420222
PL D-420223
VPO D-420224
10x14 AL D-420231
FG D-420232
PL D-420233
VPO D-420234
14x20 AL D-420241
PL D-420243
VPO D-420244

DANGER
INORGANIC ARSENIC
CANCER HAZARD
AUTHORIZED PERSONNEL ONLY
NO SMOKING OR EATING
RESPIRATOR AND PROTECTIVE
CLOTHING REQUIRED

3x5 VPO D-420314
7x10 AL D-420321
FG D-420322
PL D-420323
VPO D-420324
10x14 AL D-420331
FG D-420332
PL D-420333
VPO D-420334
14x20 AL D-420341
PL D-420343
VPO D-420344

DANGER
KEEP AWAY

3x5 VPO D-440114
7x10 AL D-440121
FG D-440122
PL D-440123
VPO D-440124
10x14 AL D-440131
FG D-440132
PL D-440133
VPO D-440134
14x20 AL D-440141
PL D-440143
VPO D-440144

DANGER
KEEP AWAY
HIGH VOLTAGE

3x5 VPO D-440214
7x10 AL D-440221
FG D-440222
PL D-440223
VPO D-440224
10x14 AL D-440231
FG D-440232
PL D-440233
VPO D-440234
14x20 AL D-440241
PL D-440243
VPO D-440244

DANGER
KEEP FINGERS
CLEAR OF MACHINE
WHILE IN MOTION

3x5 VPO D-440414
7x10 AL D-440421
FG D-440422
PL D-440423
VPO D-440424
10x14 AL D-440431
FG D-440432
PL D-440433
VPO D-440434
14x20 AL D-440441
PL D-440443
VPO D-440444

DANGER
KEEP FROM
UNDER CONVEYOR

3x5 VPO D-440514
7x10 AL D-440521
FG D-440522
PL D-440523
VPO D-440524
10x14 AL D-440531
FG D-440532
PL D-440533
VPO D-440534
14x20 AL D-440541
PL D-440543
VPO D-440544

DANGER
KEEP FROM UNDER
CRANE LOADS

3x5 VPO D-440614
7x10 AL D-440621
FG D-440622
PL D-440623
VPO D-440624
10x14 AL D-440631
FG D-440632
PL D-440633
VPO D-440634
14x20 AL D-440641
PL D-440643
VPO D-440644

DANGER
KEEP GATE
CLOSED

3x5 VPO D-440714
7x10 AL D-440721
FG D-440722
PL D-440723
VPO D-440724
10x14 AL D-440731
FG D-440732
PL D-440733
VPO D-440734
14x20 AL D-440741
PL D-440743
VPO D-440744

DANGER
KEEP HANDS
AWAY

3x5 VPO D-440814
7x10 AL D-440821
FG D-440822
PL D-440823
VPO D-440824
10x14 AL D-440831
FG D-440832
PL D-440833
VPO D-440834
14x20 AL D-440841
PL D-440843
VPO D-440844

DANGER
KEEP HANDS
CLEAR

3x5 VPO D-440914
7x10 AL D-440921
FG D-440922
PL D-440923
VPO D-440924
10x14 AL D-440931
FG D-440932
PL D-440933
VPO D-440934
14x20 AL D-440941
PL D-440943
VPO D-440944

DANGER
KEEP HANDS
CLEAR

3x5 VPO D-874114
7x10 AL D-874121
FG D-874122
PL D-874123
VPO D-874124
10x14 AL D-874131
FG D-874132
PL D-874133
VPO D-874134
14x20 AL D-874141
PL D-874143
VPO D-874144

DANGER
KEEP HANDS CLEAR
OF GATES WHEN
ELEVATOR IS IN MOTION

3x5 VPO D-441014
7x10 AL D-441021
FG D-441022
PL D-441023
VPO D-441024
10x14 AL D-441031
FG D-441032
PL D-441033
VPO D-441034
14x20 AL D-441041
PL D-441043
VPO D-441044

DANGER
KEEP HANDS CLEAR
WHEN SAW
IS OPERATING

3x5 VPO D-441114
7x10 AL D-441121
FG D-441122
PL D-441123
VPO D-441124
10x14 AL D-441131
FG D-441132
PL D-441133
VPO D-441134
14x20 AL D-441141
PL D-441143
VPO D-441144

DANGER
KEEP HANDS
OUT OF MACHINE

3x5 VPO D-441214
7x10 AL D-441221
FG D-441222
PL D-441223
VPO D-441224
10x14 AL D-441231
FG D-441232
PL D-441233
VPO D-441234
14x20 AL D-441241
PL D-441243
VPO D-441244

DANGER
KEEP HANDS
OUT OF
MOVING MACHINERY

3x5 VPO D-441314
7x10 AL D-441321
FG D-441322
PL D-441323
VPO D-441324
10x14 AL D-441331
FG D-441332
PL D-441333
VPO D-441334
14x20 AL D-441341
PL D-441343
VPO D-441344

DANGER
KEEP OFF

3x5 VPO D-441514
7x10 AL D-441521
FG D-441522
PL D-441523
VPO D-441524
10x14 AL D-441531
FG D-441532
PL D-441533
VPO D-441534
14x20 AL D-441541
PL D-441543
VPO D-441544

DANGER
KEEP OUT

3x5 VPO D-441714
7x10 AL D-441721
FG D-441722
PL D-441723
VPO D-441724
10x14 AL D-441731
FG D-441732
PL D-441733
VPO D-441734
14x20 AL D-441741
PL D-441743
VPO D-441744

DANGER
KEROSENE

3x5 VPO D-442014
7x10 AL D-442021
FG D-442022
PL D-442023
VPO D-442024
10x14 AL D-442031
FG D-442032
PL D-442033
VPO D-442034
14x20 AL D-442041
PL D-442043
VPO D-442044

DANGER
LASER

3x5 VPO D-450114
7x10 AL D-450121
FG D-450122
PL D-450123
VPO D-450124
10x14 AL D-450131
FG D-450132
PL D-450133
VPO D-450134
14x20 AL D-450141
PL D-450143
VPO D-450144

DANGER
LASER AREA
DO NOT ENTER
WHEN LIGHT IS ON

3x5 VPO D-450214
7x10 AL D-450221
FG D-450222
PL D-450223
VPO D-450224
10x14 AL D-450231
FG D-450232
PL D-450233
VPO D-450234
14x20 AL D-450241
PL D-450243
VPO D-450244

DANGER
LASER RADIATION
AVOID DIRECT EXPOSURE TO BEAM
CLASS 1/16 PRODUCT

3x5 VPO D-450314
7x10 AL D-450321
FG D-450322
PL D-450323
VPO D-450324
10x14 AL D-450331
FG D-450332
PL D-450333
VPO D-450334
14x20 AL D-450341
PL D-450343
VPO D-450344

DANGER
LASER RADIATION
AVOID EYE OR SKIN EXPOSURE
TO DIRECT OR SCATTERED RADIATION
CLASS IV LASER PRODUCT

3x5 VPO D-450414
7x10 AL D-450421
FG D-450422
PL D-450423
VPO D-450424
10x14 AL D-450431
FG D-450432
PL D-450433
VPO D-450434
14x20 AL D-450441
PL D-450443
VPO D-450444

DANGER
LIQUID
NITROGEN

3x5 VPO D-450714
7x10 AL D-450721
FG D-450722
PL D-450723
VPO D-450724
10x14 AL D-450731
FG D-450732
PL D-450733
VPO D-450734
14x20 AL D-450741
PL D-450743
VPO D-450744

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!



DANGER LIQUID OXYGEN 3x5 VPO D-450814 7x10 AL D-450821 FG D-450822 PL D-450823 VPO D-450824 10x14 AL D-450831 FG D-450832 PL D-450833 VPO D-450834 14x20 AL D-450841 PL D-450843 VPO D-450844	DANGER LOCK, TAG, CLEAR & TRY EQUIPMENT BEFORE ENTERING 3x5 VPO D-451014 7x10 AL D-451021 FG D-451022 PL D-451023 VPO D-451024 10x14 AL D-451031 FG D-451032 PL D-451033 VPO D-451034 14x20 AL D-451041 PL D-451043 VPO D-451044	DANGER LOOK OUT FOR CARS 3x5 VPO D-451214 7x10 AL D-451221 FG D-451222 PL D-451223 VPO D-451224 10x14 AL D-451231 FG D-451232 PL D-451233 VPO D-451234 14x20 AL D-451241 PL D-451243 VPO D-451244	DANGER LOOK OUT FOR CRANE 3x5 VPO D-451314 7x10 AL D-451321 FG D-451322 PL D-451323 VPO D-451324 10x14 AL D-451331 FG D-451332 PL D-451333 VPO D-451334 14x20 AL D-451341 PL D-451343 VPO D-451344	DANGER LOOK OUT FOR LIFT TRUCKS 3x5 VPO D-451414 7x10 AL D-451421 FG D-451422 PL D-451423 VPO D-451424 10x14 AL D-451431 FG D-451432 PL D-451433 VPO D-451434 14x20 AL D-451441 PL D-451443 VPO D-451444	DANGER LOOK OUT FOR MOVING CARS 3x5 VPO D-451614 7x10 AL D-451621 FG D-451622 PL D-451623 VPO D-451624 10x14 AL D-451631 FG D-451632 PL D-451633 VPO D-451634 14x20 AL D-451641 PL D-451643 VPO D-451644	DANGER LOOK OUT FOR TRUCKS 3x5 VPO D-451714 7x10 AL D-451721 FG D-451722 PL D-451723 VPO D-451724 10x14 AL D-451731 FG D-451732 PL D-451733 VPO D-451734 14x20 AL D-451741 PL D-451743 VPO D-451744
--	--	--	---	---	---	--

DANGER LOW CLEARANCE 3x5 VPO D-451914 7x10 AL D-451921 FG D-451922 PL D-451923 VPO D-451924 10x14 AL D-451931 FG D-451932 PL D-451933 VPO D-451934 14x20 AL D-451941 PL D-451943 VPO D-451944	DANGER LOW OVERHEAD CLEARANCE 3x5 VPO D-452014 7x10 AL D-452021 FG D-452022 PL D-452023 VPO D-452024 10x14 AL D-452031 FG D-452032 PL D-452033 VPO D-452034 14x20 AL D-452041 PL D-452043 VPO D-452044	DANGER LP GAS STORAGE NO SMOKING OR OPEN FLAMES WITHIN 50 FT. 3x5 VPO D-452114 7x10 AL D-452121 FG D-452122 PL D-452123 VPO D-452124 10x14 AL D-452131 FG D-452132 PL D-452133 VPO D-452134 14x20 AL D-452141 PL D-452143 VPO D-452144	DANGER MACHINERY IN USE 3x5 VPO D-460114 7x10 AL D-460121 FG D-460122 PL D-460123 VPO D-460124 10x14 AL D-460131 FG D-460132 PL D-460133 VPO D-460134 14x20 AL D-460141 PL D-460143 VPO D-460144	DANGER MAN WORKING ON CRANE 3x5 VPO D-460314 7x10 AL D-460321 FG D-460322 PL D-460323 VPO D-460324 10x14 AL D-460331 FG D-460332 PL D-460333 VPO D-460334 14x20 AL D-460341 PL D-460343 VPO D-460344	DANGER MAN WORKING ON LINE DON'T THROW SWITCH 3x5 VPO D-460414 7x10 AL D-460421 FG D-460422 PL D-460423 VPO D-460424 10x14 AL D-460431 FG D-460432 PL D-460433 VPO D-460434 14x20 AL D-460441 PL D-460443 VPO D-460444	DANGER MATERIAL MAY BE HOT 3x5 VPO D-923914 7x10 AL D-923921 FG D-923922 PL D-923923 VPO D-923924 10x14 AL D-923931 FG D-923932 PL D-923933 VPO D-923934 14x20 AL D-923941 PL D-923943 VPO D-923944
--	---	--	---	---	---	--

DANGER MEN AT WORK 3x5 VPO D-460514 7x10 AL D-460521 FG D-460522 PL D-460523 VPO D-460524 10x14 AL D-460531 FG D-460532 PL D-460533 VPO D-460534 14x20 AL D-460541 PL D-460543 VPO D-460544	DANGER MEN WORKING 3x5 VPO D-460614 7x10 AL D-460621 FG D-460622 PL D-460623 VPO D-460624 10x14 AL D-460631 FG D-460632 PL D-460633 VPO D-460634 14x20 AL D-460641 PL D-460643 VPO D-460644	DANGER MEN WORKING ABOVE 3x5 VPO D-460714 7x10 AL D-460721 FG D-460722 PL D-460723 VPO D-460724 10x14 AL D-460731 FG D-460732 PL D-460733 VPO D-460734 14x20 AL D-460741 PL D-460743 VPO D-460744	DANGER MEN WORKING BELOW 3x5 VPO D-460814 7x10 AL D-460821 FG D-460822 PL D-460823 VPO D-460824 10x14 AL D-460831 FG D-460832 PL D-460833 VPO D-460834 14x20 AL D-460841 PL D-460843 VPO D-460844	DANGER MEN WORKING DO NOT ENTER 3x5 VPO D-461114 7x10 AL D-461121 FG D-461122 PL D-461123 VPO D-461124 10x14 AL D-461131 FG D-461132 PL D-461133 VPO D-461134 14x20 AL D-461141 PL D-461143 VPO D-461144	DANGER MEN WORKING DON'T START 3x5 VPO D-461214 7x10 AL D-461221 FG D-461222 PL D-461223 VPO D-461224 10x14 AL D-461231 FG D-461232 PL D-461233 VPO D-461234 14x20 AL D-461241 PL D-461243 VPO D-461244	DANGER MEN WORKING INSIDE 3x5 VPO D-461314 7x10 AL D-461321 FG D-461322 PL D-461323 VPO D-461324 10x14 AL D-461331 FG D-461332 PL D-461333 VPO D-461334 14x20 AL D-461341 PL D-461343 VPO D-461344
--	--	---	---	---	--	---

DANGER MEN WORKING OVERHEAD 3x5 VPO D-461414 7x10 AL D-461421 FG D-461422 PL D-461423 VPO D-461424 10x14 AL D-461431 FG D-461432 PL D-461433 VPO D-461434 14x20 AL D-461441 PL D-461443 VPO D-461444	DANGER METHANOL 3x5 VPO D-461614 7x10 AL D-461621 FG D-461622 PL D-461623 VPO D-461624 10x14 AL D-461631 FG D-461632 PL D-461633 VPO D-461634 14x20 AL D-461641 PL D-461643 VPO D-461644	DANGER MICROWAVE FREQUENCIES PRESENT 3x5 VPO D-461714 7x10 AL D-461721 FG D-461722 PL D-461723 VPO D-461724 10x14 AL D-461731 FG D-461732 PL D-461733 VPO D-461734 14x20 AL D-461741 PL D-461743 VPO D-461744	DANGER MICROWAVE OVEN PERSONS WEARING PACEMAKER SHOULD NOT ENTER BUILDING 3x5 VPO D-461814 7x10 AL D-461821 FG D-461822 PL D-461823 VPO D-461824 10x14 AL D-461831 FG D-461832 PL D-461833 VPO D-461834 14x20 AL D-461841 PL D-461843 VPO D-461844	DANGER MOLTEN LEAD 3x5 VPO D-462014 7x10 AL D-462021 FG D-462022 PL D-462023 VPO D-462024 10x14 AL D-462031 FG D-462032 PL D-462033 VPO D-462034 14x20 AL D-462041 PL D-462043 VPO D-462044	DANGER MOVING EQUIPMENT STARTS WITHOUT WARNING 3x5 VPO D-462114 7x10 AL D-462121 FG D-462122 PL D-462123 VPO D-462124 10x14 AL D-462131 FG D-462132 PL D-462133 VPO D-462134 14x20 AL D-462141 PL D-462143 VPO D-462144	DANGER MOVING MACHINERY 3x5 VPO D-462214 7x10 AL D-462221 FG D-462222 PL D-462223 VPO D-462224 10x14 AL D-462231 FG D-462232 PL D-462233 VPO D-462234 14x20 AL D-462241 PL D-462243 VPO D-462244
---	---	--	---	--	--	---

THE SIGNS OF A SAFE INDUSTRY

MATERIALS



 MOVING PARTS 3x5 VPO D-923314 7x10 AL D-923321 FG D-923322 PL D-923323 VPO D-923324 10x14 AL D-923331 FG D-923332 PL D-923333 VPO D-923334 14x20 AL D-923341 PL D-923343 VPO D-923344	 NAPHTHA 3x5 VPO D-470114 7x10 AL D-470121 FG D-470122 PL D-470123 VPO D-470124 10x14 AL D-470131 FG D-470132 PL D-470133 VPO D-470134 14x20 AL D-470141 PL D-470143 VPO D-470144	 NIP POINTS 3x5 VPO D-470214 7x10 AL D-470221 FG D-470222 PL D-470223 VPO D-470224 10x14 AL D-470231 FG D-470232 PL D-470233 VPO D-470234 14x20 AL D-470241 PL D-470243 VPO D-470244	 NITRIC ACID 3x5 VPO D-470314 7x10 AL D-470321 FG D-470322 PL D-470323 VPO D-470324 10x14 AL D-470331 FG D-470332 PL D-470333 VPO D-470334 14x20 AL D-470341 PL D-470343 VPO D-470344	 NITROGEN 3x5 VPO D-470414 7x10 AL D-470421 FG D-470422 PL D-470423 VPO D-470424 10x14 AL D-470431 FG D-470432 PL D-470433 VPO D-470434 14x20 AL D-470441 PL D-470443 VPO D-470444	 NITROGEN DIOXIDE 3x5 VPO D-470514 7x10 AL D-470521 FG D-470522 PL D-470523 VPO D-470524 10x14 AL D-470531 FG D-470532 PL D-470533 VPO D-470534 14x20 AL D-470541 PL D-470543 VPO D-470544	 NO ADMITTANCE 3x5 VPO D-470614 7x10 AL D-470621 FG D-470622 PL D-470623 VPO D-470624 10x14 AL D-470631 FG D-470632 PL D-470633 VPO D-470634 14x20 AL D-470641 PL D-470643 VPO D-470644
--	---	--	---	--	--	---

 NO ADMITTANCE EXCEPT TO EMPLOYEES ON DUTY 3x5 VPO D-470714 7x10 AL D-470721 FG D-470722 PL D-470723 VPO D-470724 10x14 AL D-470731 FG D-470732 PL D-470733 VPO D-470734 14x20 AL D-470741 PL D-470743 VPO D-470744	 NO ADMITTANCE WHEN EQUIPMENT IS OPERATING 3x5 VPO D-470914 7x10 AL D-470921 FG D-470922 PL D-470923 VPO D-470924 10x14 AL D-470931 FG D-470932 PL D-470933 VPO D-470934 14x20 AL D-470941 PL D-470943 VPO D-470944	 NO ADMITTANCE WHILE MACHINE IN OPERATION 3x5 VPO D-471014 7x10 AL D-471021 FG D-471022 PL D-471023 VPO D-471024 10x14 AL D-471031 FG D-471032 PL D-471033 VPO D-471034 14x20 AL D-471041 PL D-471043 VPO D-471044	 NO ADMITTANCE WITHOUT A PERMIT 3x5 VPO D-471114 7x10 AL D-471121 FG D-471122 PL D-471123 VPO D-471124 10x14 AL D-471131 FG D-471132 PL D-471133 VPO D-471134 14x20 AL D-471141 PL D-471143 VPO D-471144	 NO BURNING, WELDING OR OPEN FLAMES WITHOUT PERMISSION 3x5 VPO D-471214 7x10 AL D-471221 FG D-471222 PL D-471223 VPO D-471224 10x14 AL D-471231 FG D-471232 PL D-471233 VPO D-471234 14x20 AL D-471241 PL D-471243 VPO D-471244	 NO CLEARANCE 3x5 VPO D-471314 7x10 AL D-471321 FG D-471322 PL D-471323 VPO D-471324 10x14 AL D-471331 FG D-471332 PL D-471333 VPO D-471334 14x20 AL D-471341 PL D-471343 VPO D-471344	 NO CLEARANCE FOR MAN ON CAR 3x5 VPO D-471414 7x10 AL D-471421 FG D-471422 PL D-471423 VPO D-471424 10x14 AL D-471431 FG D-471432 PL D-471433 VPO D-471434 14x20 AL D-471441 PL D-471443 VPO D-471444
---	---	--	--	---	--	---

 NO FISHING, BOATING, SWIMMING STRONG UNDERCURRENT 3x5 VPO D-471514 7x10 AL D-471521 FG D-471522 PL D-471523 VPO D-471524 10x14 AL D-471531 FG D-471532 PL D-471533 VPO D-471534 14x20 AL D-471541 PL D-471543 VPO D-471544	 NO FLAMMABLE LIQUIDS BEYOND THIS POINT 3x5 VPO D-471614 7x10 AL D-471621 FG D-471622 PL D-471623 VPO D-471624 10x14 AL D-471631 FG D-471632 PL D-471633 VPO D-471634 14x20 AL D-471641 PL D-471643 VPO D-471644	 NO LIFT TRUCKS ALLOWED ON PLATFORM 3x5 VPO D-471714 7x10 AL D-471721 FG D-471722 PL D-471723 VPO D-471724 10x14 AL D-471731 FG D-471732 PL D-471733 VPO D-471734 14x20 AL D-471741 PL D-471743 VPO D-471744	 NO OPEN BURNING 3x5 VPO D-471814 7x10 AL D-471821 FG D-471822 PL D-471823 VPO D-471824 10x14 AL D-471831 FG D-471832 PL D-471833 VPO D-471834 14x20 AL D-471841 PL D-471843 VPO D-471844	 NO OPEN FLAMES 3x5 VPO D-471914 7x10 AL D-471921 FG D-471922 PL D-471923 VPO D-471924 10x14 AL D-471931 FG D-471932 PL D-471933 VPO D-471934 14x20 AL D-471941 PL D-471943 VPO D-471944	 NO PEDESTRIAN TRAFFIC 3x5 VPO D-472114 7x10 AL D-472121 FG D-472122 PL D-472123 VPO D-472124 10x14 AL D-472131 FG D-472132 PL D-472133 VPO D-472134 14x20 AL D-472141 PL D-472143 VPO D-472144	 NO RIDERS 3x5 VPO D-472214 7x10 AL D-472221 FG D-472222 PL D-472223 VPO D-472224 10x14 AL D-472231 FG D-472232 PL D-472233 VPO D-472234 14x20 AL D-472241 PL D-472243 VPO D-472244
---	--	--	---	--	---	---

 NO SMOKING 3x5 VPO D-472314 7x10 AL D-472321 FG D-472322 PL D-472323 VPO D-472324 10x14 AL D-472331 FG D-472332 PL D-472333 VPO D-472334 14x20 AL D-472341 PL D-472343 VPO D-472344	 NO SMOKING BATTERY CHARGING AREA 3x5 VPO D-472514 7x10 AL D-472521 FG D-472522 PL D-472523 VPO D-472524 10x14 AL D-472531 FG D-472532 PL D-472533 VPO D-472534 14x20 AL D-472541 PL D-472543 VPO D-472544	 NO SMOKING BATTERY CHARGING EMITS HYDROGEN GAS 3x5 VPO D-472614 7x10 AL D-472621 FG D-472622 PL D-472623 VPO D-472624 10x14 AL D-472631 FG D-472632 PL D-472633 VPO D-472634 14x20 AL D-472641 PL D-472643 VPO D-472644	 NO SMOKING BEYOND THIS DOOR 3x5 VPO D-472714 7x10 AL D-472721 FG D-472722 PL D-472723 VPO D-472724 10x14 AL D-472731 FG D-472732 PL D-472733 VPO D-472734 14x20 AL D-472741 PL D-472743 VPO D-472744	 NO SMOKING BEYOND THIS POINT 3x5 VPO D-472914 7x10 AL D-472921 FG D-472922 PL D-472923 VPO D-472924 10x14 AL D-472931 FG D-472932 PL D-472933 VPO D-472934 14x20 AL D-472941 PL D-472943 VPO D-472944	 NO SMOKING EXPLOSIVE GAS 3x5 VPO D-473114 7x10 AL D-473121 FG D-473122 PL D-473123 VPO D-473124 10x14 AL D-473131 FG D-473132 PL D-473133 VPO D-473134 14x20 AL D-473141 PL D-473143 VPO D-473144	 NO SMOKING FLAME OR SPARK PRODUCING DEVICES IN THIS AREA 3x5 VPO D-473214 7x10 AL D-473221 FG D-473222 PL D-473223 VPO D-473224 10x14 AL D-473231 FG D-473232 PL D-473233 VPO D-473234 14x20 AL D-473241 PL D-473243 VPO D-473244
--	--	--	---	--	--	--

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!



DANGER
NO SMOKING
FLAMMABLE LIQUID

3x5 VPO D-473314
7x10 AL D-473321
FG D-473322
PL D-473323
VPO D-473324
10x14 AL D-473331
FG D-473332
PL D-473333
VPO D-473334
14x20 AL D-473341
PL D-473343
VPO D-473344

DANGER
NO SMOKING
IN THIS AREA

3x5 VPO D-473414
7x10 AL D-473421
FG D-473422
PL D-473423
VPO D-473424
10x14 AL D-473431
FG D-473432
PL D-473433
VPO D-473434
14x20 AL D-473441
PL D-473443
VPO D-473444

DANGER
NO SMOKING
IN TRAILERS
OR DOCK AREA

3x5 VPO D-473614
7x10 AL D-473621
FG D-473622
PL D-473623
VPO D-473624
10x14 AL D-473631
FG D-473632
PL D-473633
VPO D-473634
14x20 AL D-473641
PL D-473643
VPO D-473644

DANGER
NO SMOKING
LP GAS

3x5 VPO D-473714
7x10 AL D-473721
FG D-473722
PL D-473723
VPO D-473724
10x14 AL D-473731
FG D-473732
PL D-473733
VPO D-473734
14x20 AL D-473741
PL D-473743
VPO D-473744

DANGER
NO SMOKING
MATCHES OR
OPEN FLAMES

3x5 VPO D-473814
7x10 AL D-473821
FG D-473822
PL D-473823
VPO D-473824
10x14 AL D-473831
FG D-473832
PL D-473833
VPO D-473834
14x20 AL D-473841
PL D-473843
VPO D-473844

DANGER
NO SMOKING
MATCHES OR
OPEN LIGHTS

3x5 VPO D-473914
7x10 AL D-473921
FG D-473922
PL D-473923
VPO D-473924
10x14 AL D-473931
FG D-473932
PL D-473933
VPO D-473934
14x20 AL D-473941
PL D-473943
VPO D-473944

DANGER
NO SMOKING
NO OPEN FLAMES
NO SPARKS

3x5 VPO D-474114
7x10 AL D-474121
FG D-474122
PL D-474123
VPO D-474124
10x14 AL D-474131
FG D-474132
PL D-474133
VPO D-474134
14x20 AL D-474141
PL D-474143
VPO D-474144

DANGER
NO SMOKING
OR
OPEN FLAMES

3x5 VPO D-474214
7x10 AL D-474221
FG D-474222
PL D-474223
VPO D-474224
10x14 AL D-474231
FG D-474232
PL D-474233
VPO D-474234
14x20 AL D-474241
PL D-474243
VPO D-474244

DANGER
NO SMOKING OR
OPEN FLAMES
IN THIS AREA

3x5 VPO D-474314
7x10 AL D-474321
FG D-474322
PL D-474323
VPO D-474324
10x14 AL D-474331
FG D-474332
PL D-474333
VPO D-474334
14x20 AL D-474341
PL D-474343
VPO D-474344

DANGER
NO SMOKING OR
OPEN FLAMES WHEN
CHARGING BATTERIES

3x5 VPO D-474414
7x10 AL D-474421
FG D-474422
PL D-474423
VPO D-474424
10x14 AL D-474431
FG D-474432
PL D-474433
VPO D-474434
14x20 AL D-474441
PL D-474443
VPO D-474444

DANGER
NO SMOKING OR
OPEN FLAMES
WITHIN 50 FEET

3x5 VPO D-474514
7x10 AL D-474521
FG D-474522
PL D-474523
VPO D-474524
10x14 AL D-474531
FG D-474532
PL D-474533
VPO D-474534
14x20 AL D-474541
PL D-474543
VPO D-474544

DANGER
NO SMOKING
OXYGEN IN USE

3x5 VPO D-474714
7x10 AL D-474721
FG D-474722
PL D-474723
VPO D-474724
10x14 AL D-474731
FG D-474732
PL D-474733
VPO D-474734
14x20 AL D-474741
PL D-474743
VPO D-474744

DANGER
NO SMOKING
PROPANE

3x5 VPO D-475014
7x10 AL D-475021
FG D-475022
PL D-475023
VPO D-475024
10x14 AL D-475031
FG D-475032
PL D-475033
VPO D-475034
14x20 AL D-475041
PL D-475043
VPO D-475044

DANGER
NO SMOKING
WELDING FLAMES MATCHES
OPEN LIGHTS SPARKS
FLAMMABLE

3x5 VPO D-475114
7x10 AL D-475121
FG D-475122
PL D-475123
VPO D-475124
10x14 AL D-475131
FG D-475132
PL D-475133
VPO D-475134
14x20 AL D-475141
PL D-475143
VPO D-475144

DANGER
NO SMOKING
WELDING OR
OPEN FLAMES

3x5 VPO D-475214
7x10 AL D-475221
FG D-475222
PL D-475223
VPO D-475224
10x14 AL D-475231
FG D-475232
PL D-475233
VPO D-475234
14x20 AL D-475241
PL D-475243
VPO D-475244

DANGER
NO SMOKING
WITHIN 15 FEET

3x5 VPO D-475314
7x10 AL D-475321
FG D-475322
PL D-475323
VPO D-475324
10x14 AL D-475331
FG D-475332
PL D-475333
VPO D-475334
14x20 AL D-475341
PL D-475343
VPO D-475344

DANGER
NO SMOKING
WITHIN 25 FEET

3x5 VPO D-475414
7x10 AL D-475421
FG D-475422
PL D-475423
VPO D-475424
10x14 AL D-475431
FG D-475432
PL D-475433
VPO D-475434
14x20 AL D-475441
PL D-475443
VPO D-475444

DANGER
NO
TRESPASSING

3x5 VPO D-475614
7x10 AL D-475621
FG D-475622
PL D-475623
VPO D-475624
10x14 AL D-475631
FG D-475632
PL D-475633
VPO D-475634
14x20 AL D-475641
PL D-475643
VPO D-475644

DANGER
NO WELDING
OR OPEN FLAMES

3x5 VPO D-475814
7x10 AL D-475821
FG D-475822
PL D-475823
VPO D-475824
10x14 AL D-475831
FG D-475832
PL D-475833
VPO D-475834
14x20 AL D-475841
PL D-475843
VPO D-475844

DANGER
OPEN
EXCAVATION

3x5 VPO D-570114
7x10 AL D-570121
FG D-570122
PL D-570123
VPO D-570124
10x14 AL D-570131
FG D-570132
PL D-570133
VPO D-570134
14x20 AL D-570141
PL D-570143
VPO D-570144

DANGER
OPEN FLAME

3x5 VPO D-570214
7x10 AL D-570221
FG D-570222
PL D-570223
VPO D-570224
10x14 AL D-570231
FG D-570232
PL D-570233
VPO D-570234
14x20 AL D-570241
PL D-570243
VPO D-570244

DANGER
OPEN HOLE

3x5 VPO D-570314
7x10 AL D-570321
FG D-570322
PL D-570323
VPO D-570324
10x14 AL D-570331
FG D-570332
PL D-570333
VPO D-570334
14x20 AL D-570341
PL D-570343
VPO D-570344

DANGER
OPEN PIT

3x5 VPO D-570414
7x10 AL D-570421
FG D-570422
PL D-570423
VPO D-570424
10x14 AL D-570431
FG D-570432
PL D-570433
VPO D-570434
14x20 AL D-570441
PL D-570443
VPO D-570444

DANGER
OPEN TRENCH

3x5 VPO D-570614
7x10 AL D-570621
FG D-570622
PL D-570623
VPO D-570624
10x14 AL D-570631
FG D-570632
PL D-570633
VPO D-570634
14x20 AL D-570641
PL D-570643
VPO D-570644

DANGER
OUT OF SERVICE
DO NOT START

3x5 VPO D-570814
7x10 AL D-570821
FG D-570822
PL D-570823
VPO D-570824
10x14 AL D-570831
FG D-570832
PL D-570833
VPO D-570834
14x20 AL D-570841
PL D-570843
VPO D-570844

DANGER
OVERHEAD
CONVEYOR

3x5 VPO D-570914
7x10 AL D-570921
FG D-570922
PL D-570923
VPO D-570924
10x14 AL D-570931
FG D-570932
PL D-570933
VPO D-570934
14x20 AL D-570941
PL D-570943
VPO D-570944

DANGER
OVERHEAD
CRANE

3x5 VPO D-923214
7x10 AL D-923221
FG D-923222
PL D-923223
VPO D-923224
10x14 AL D-923231
FG D-923232
PL D-923233
VPO D-923234
14x20 AL D-923241
PL D-923243
VPO D-923244

DANGER
OVERHEAD
HOIST

3x5 VPO D-571114
7x10 AL D-571121
FG D-571122
PL D-571123
VPO D-571124
10x14 AL D-571131
FG D-571132
PL D-571133
VPO D-571134
14x20 AL D-571141
PL D-571143
VPO D-571144

THE SIGNS OF A SAFE INDUSTRY



DANGER OVERHEAD POWER LINES	DANGER OVERHEAD WORK DO NOT ENTER	DANGER OXYGEN	DANGER OXYGEN NO SMOKING	DANGER OXYGEN NO SMOKING NO OPEN FLAME	DANGER OXYGEN STORAGE NO SMOKING NO OPEN FLAME	DANGER PANEL CONTAINS MORE THAN ONE SOURCE OF VOLTAGE
3x5 VPO D-571214 7x10 AL D-571221 FG D-571222 PL D-571223 VPO D-571224 10x14 AL D-571231 FG D-571232 PL D-571233 VPO D-571234 14x20 AL D-571241 PL D-571243 VPO D-571244	3x5 VPO D-571314 7x10 AL D-571321 FG D-571322 PL D-571323 VPO D-571324 10x14 AL D-571331 FG D-571332 PL D-571333 VPO D-571334 14x20 AL D-571341 PL D-571343 VPO D-571344	3x5 VPO D-571414 7x10 AL D-571421 FG D-571422 PL D-571423 VPO D-571424 10x14 AL D-571431 FG D-571432 PL D-571433 VPO D-571434 14x20 AL D-571441 PL D-571443 VPO D-571444	3x5 VPO D-571614 7x10 AL D-571621 FG D-571622 PL D-571623 VPO D-571624 10x14 AL D-571631 FG D-571632 PL D-571633 VPO D-571634 14x20 AL D-571641 PL D-571643 VPO D-571644	3x5 VPO D-571714 7x10 AL D-571721 FG D-571722 PL D-571723 VPO D-571724 10x14 AL D-571731 FG D-571732 PL D-571733 VPO D-571734 14x20 AL D-571741 PL D-571743 VPO D-571744	3x5 VPO D-571814 7x10 AL D-571821 FG D-571822 PL D-571823 VPO D-571824 10x14 AL D-571831 FG D-571832 PL D-571833 VPO D-571834 14x20 AL D-571841 PL D-571843 VPO D-571844	3x5 VPO D-600314 7x10 AL D-600321 FG D-600322 PL D-600323 VPO D-600324 10x14 AL D-600331 FG D-600332 PL D-600333 VPO D-600334 14x20 AL D-600341 PL D-600343 VPO D-600344

DANGER PCB REPORT LEAKS OR SPILLS IMMEDIATELY TO MAINTENANCE SUPERINTENDENT	DANGER PERSONAL PROTECTIVE EQUIPMENT IS TO BE USED AT ALL TIMES WHEN HANDLING CHEMICALS	DANGER PESTICIDE STORAGE	DANGER PESTICIDE STORAGE AUTHORIZED PERSONNEL ONLY	DANGER PESTICIDES IN TANK KEEP OFF	DANGER PESTICIDE STORAGE AREA	DANGER PETROLEUM PRODUCTS
3x5 VPO D-601914 7x10 AL D-601921 FG D-601922 PL D-601923 VPO D-601924 10x14 AL D-601931 FG D-601932 PL D-601933 VPO D-601934 14x20 AL D-601941 PL D-601943 VPO D-601944	3x5 VPO D-600414 7x10 AL D-600421 FG D-600422 PL D-600423 VPO D-600424 10x14 AL D-600431 FG D-600432 PL D-600433 VPO D-600434 14x20 AL D-600441 PL D-600443 VPO D-600444	3x5 VPO D-600514 7x10 AL D-600521 FG D-600522 PL D-600523 VPO D-600524 10x14 AL D-600531 FG D-600532 PL D-600533 VPO D-600534 14x20 AL D-600541 PL D-600543 VPO D-600544	3x5 VPO D-998514 7x10 AL D-998521 FG D-998522 PL D-998523 VPO D-998524 10x14 AL D-998531 FG D-998532 PL D-998533 VPO D-998534 14x20 AL D-998541 PL D-998543 VPO D-998544	3x5 VPO D-998314 7x10 AL D-998321 FG D-998322 PL D-998323 VPO D-998324 10x14 AL D-998331 FG D-998332 PL D-998333 VPO D-998334 14x20 AL D-998341 PL D-998343 VPO D-998344	3x5 VPO D-998414 7x10 AL D-998421 FG D-998422 PL D-998423 VPO D-998424 10x14 AL D-998431 FG D-998432 PL D-998433 VPO D-998434 14x20 AL D-998441 PL D-998443 VPO D-998444	3x5 VPO D-923414 7x10 AL D-923421 FG D-923422 PL D-923423 VPO D-923424 10x14 AL D-923431 FG D-923432 PL D-923433 VPO D-923434 14x20 AL D-923441 PL D-923443 VPO D-923444

DANGER PINCH POINT	DANGER PINCH POINTS	DANGER POISON	DANGER POISON GAS	DANGER POISON PESTICIDE STORAGE AREA AUTHORIZED PERSONNEL ONLY	DANGER POSSIBLE ASPHYXIATING ATMOSPHERE BEYOND THIS POINT	DANGER PRESSURE 30 PSI MAXIMUM PRESSURE ALLOWED FOR CLEANING WITH COMPRESSED AIR
3x5 VPO D-874414 7x10 AL D-874421 FG D-874422 PL D-874423 VPO D-874424 10x14 AL D-874431 FG D-874432 PL D-874433 VPO D-874434 14x20 AL D-874441 PL D-874443 VPO D-874444	3x5 VPO D-600714 7x10 AL D-600721 FG D-600722 PL D-600723 VPO D-600724 10x14 AL D-600731 FG D-600732 PL D-600733 VPO D-600734 14x20 AL D-600741 PL D-600743 VPO D-600744	3x5 VPO D-600814 7x10 AL D-600821 FG D-600822 PL D-600823 VPO D-600824 10x14 AL D-600831 FG D-600832 PL D-600833 VPO D-600834 14x20 AL D-600841 PL D-600843 VPO D-600844	3x5 VPO D-601014 7x10 AL D-601021 FG D-601022 PL D-601023 VPO D-601024 10x14 AL D-601031 FG D-601032 PL D-601033 VPO D-601034 14x20 AL D-601041 PL D-601043 VPO D-601044	3x5 VPO D-601114 7x10 AL D-601121 FG D-601122 PL D-601123 VPO D-601124 10x14 AL D-601131 FG D-601132 PL D-601133 VPO D-601134 14x20 AL D-601141 PL D-601143 VPO D-601144	3x5 VPO D-601214 7x10 AL D-601221 FG D-601222 PL D-601223 VPO D-601224 10x14 AL D-601231 FG D-601232 PL D-601233 VPO D-601234 14x20 AL D-601241 PL D-601243 VPO D-601244	3x5 VPO D-601414 7x10 AL D-601421 FG D-601422 PL D-601423 VPO D-601424 10x14 AL D-601431 FG D-601432 PL D-601433 VPO D-601434 14x20 AL D-601441 PL D-601443 VPO D-601444

DANGER PROPANE GAS	DANGER PROPANE GAS NO SMOKING AUTHORIZED PERSONNEL ONLY	DANGER PROTECTIVE EQUIPMENT MUST BE WORN IN THIS AREA AT ALL TIMES	DANGER PUMP STARTS AUTOMATICALLY	DANGER RESPIRATOR REQUIRED	DANGER RESPIRATORS REQUIRED IN THIS AREA	DANGER RESTRICTED AREA
3x5 VPO D-601514 7x10 AL D-601521 FG D-601522 PL D-601523 VPO D-601524 10x14 AL D-601531 FG D-601532 PL D-601533 VPO D-601534 14x20 AL D-601541 PL D-601543 VPO D-601544	3x5 VPO D-601614 7x10 AL D-601621 FG D-601622 PL D-601623 VPO D-601624 10x14 AL D-601631 FG D-601632 PL D-601633 VPO D-601634 14x20 AL D-601641 PL D-601643 VPO D-601644	3x5 VPO D-601714 7x10 AL D-601721 FG D-601722 PL D-601723 VPO D-601724 10x14 AL D-601731 FG D-601732 PL D-601733 VPO D-601734 14x20 AL D-601741 PL D-601743 VPO D-601744	3x5 VPO D-601814 7x10 AL D-601821 FG D-601822 PL D-601823 VPO D-601824 10x14 AL D-601831 FG D-601832 PL D-601833 VPO D-601834 14x20 AL D-601841 PL D-601843 VPO D-601844	3x5 VPO D-660214 7x10 AL D-660221 FG D-660222 PL D-660223 VPO D-660224 10x14 AL D-660231 FG D-660232 PL D-660233 VPO D-660234 14x20 AL D-660241 PL D-660243 VPO D-660244	3x5 VPO D-660314 7x10 AL D-660321 FG D-660322 PL D-660323 VPO D-660324 10x14 AL D-660331 FG D-660332 PL D-660333 VPO D-660334 14x20 AL D-660341 PL D-660343 VPO D-660344	3x5 VPO D-660414 7x10 AL D-660421 FG D-660422 PL D-660423 VPO D-660424 10x14 AL D-660431 FG D-660432 PL D-660433 VPO D-660434 14x20 AL D-660441 PL D-660443 VPO D-660444

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!